
This is a CAD produced drawing - do **NOT** alter manually.

© This Drawing is copyright of LDN Architects LLP

PROPOSED WORKS TO THE SOUTH TOWER ROOFS

- Overhaul existing slate roofs comprising large format slates in even courses typical of a William Burn roof. Provide additional discrete ventilation to pitches.
 Overhaul existing LSA compliant leadwork including timber cored ridge rolls, lead valleys, lead flat roofs within turrets and parapet gutters.



Rev A 2021.02.26 01. Existing Roof Plan updated

Rev B 2021.03.18 MS 01. Roof S.R11 (between ST Court & Link Building) updated

LDN Architects

29 St Leonards Road, Forres IV36 1EN T: 01309 673 221 E: architects@ldn.co.uk

INVERNESS CASTLE

Drawing Title: PROPOSED Roof Plan

Drawing Status: PLANNING & LISTED BUILDING CONSENT

Drawing Number: F1902 MW L(--) 007 1:100 @ A1 1:200 @ A3 Oct 2020

Do **NOT** scale from this drawing. If unsure of dimensions then ask LDN Architects. All dimensions are shown in millimetres unless otherwise stated. This is a CAD produced drawing - do **NOT** alter manually.

© This Drawing is copyright of LDN Architects LLP

PROPOSED WORKS TO THE NORTH TOWER ROOF

- Overhaul existing slate roofs comprising Scots slates laid in diminishing courses.
 Overhaul existing LSA compliant leadwork including timber cored ridge rolls, lead
- valleys and parapet gutters. • Overhaul existing cast iron roof lights and lead clad timber lanterns.
- Provide additional maintenance access to parapet gutters via conservation type rooflights set behind parapets.
- No work proposed to existing glass pavilion and access deck on NW corner tower. Overhaul existing chimneys where out with work completed in 2016 and install ventilators to unused flues.
- Check compliance of existing Lightning Protection System.
 Integrate existing parapet level floodlighting scheme into new proposals.
 Repoint all parapets where mortar is friable.

RAINWATER GOODS ETC:

- Overhaul existing cast iron system and enlarge downpipes where appropriate to equip the system for climate change, including redecoration.
- Rationalise soil system to remove extraneous pipework from facades.



- Overhaul existing slate roofs comprising Scots slates laid in diminishing courses.
- Overhaul existing LSA compliant leadwork including timber cored ridge rolls, lead valleys and parapet gutters.
 Overhaul existing cast iron roof lights and lead clad timber lanterns.
- Provide additional maintenance access to parapet gutters via conservation type rooflights set behind parapets.
- No work proposed to existing glass pavilion and access deck on NW corner tower.
 Overhaul existing chimneys where out with work completed in 2016 and install ventilators to unused flues.
- Check compliance of existing Lightning Protection System.
 Integrate existing parapet level floodlighting scheme into new proposals.
- Repoint all parapets where mortar is friable.

MASONRY WORKS:

- MASONRY WORKS:
 The general rubble walling which is squared and partially brought to courses has a rough stugged (tooled) surface.
 The ashlar quoins, window dressings and base course in matching stone have a finer tooling with a droved finish to the margins.
 Window and door margins are chamfered. Stringcourses are generally quite simple with angled top surfaces and well undercut, providing good run off.
 The masonry is a local pink hued Black Isle conglomerate. Depending on its exposure to weather, it has lost its surface and exhibits crumbling, flaking, granular disintegration due to salts, binder dissolution and exfoliation along grain boundaries. We also see some cuboidal cracking due to clay expansion.
 Part of this elevation associated with the Viewing Tower was the subject of a masonry repair and repointing contract in 2016. This was undertaken using a hydraulic lime mortar and a combination of stone indenting using Lazenby stone and plastic repairs on the highest tower. The remainder of the facades are cement pointed but retain the earlier lime mortar.
 The proposal is to extend the existing repair scheme across the remainder of the building using a suitable source of matching stone subject to the results of a stone and mortar analysis report to be commissioned as part of the detailed design work. See Fabric report for extent of intervention.
 The new doorway is to be detailed to match the existing
- The new doorway is to be detailed to match the existing.

WINDOW WORKS:

- Windows to be replaced with new sash and case windows with thin double glazing. Fenestration to match existing. See detailed condition report.
- Existing external doors to be overhauled.
- Window and door colours to be the subject of historic paint investigation but windows provisionally to be painted a darker colour rather than white as at present, subject to agreement of sample for new overall decorative scheme for woodwork and cast iron.
- Window bars to be retained, treated and repainted.

RAINWATER GOODS ETC:

• Overhaul existing cast iron system and enlarge downpipes where appropriate to equip the system for climate change, including redecoration. Rationalise soil system to remove extraneous pipework from facades.

ANCILLARY WALLS:

• The existing mass masonry retaining bastion walls are to be raked out and repointed using a hydraulic mortar with limited stone indenting. A suitable source of matching stone and mortar will be subject to the results of a stone and mortar analysis report to be commissioned as part of the detailed design work.

2021.03.23 01. Link Building entrance arrangement updated

LDN Architects

29 St Leonards Road, Forres IV36 1EN T: 01309 673 221 E: architects@ldn.co.uk

INVERNESS CASTLE

Drawing Title: PROPOSED North Elevation

Drawing Status: Planning & Listed Building Consent

Drawing Number: F1902 MW L(--) 011 1:100 @ A1 Oct 2020 1:200 @ A3

Do **NOT** scale from this drawing. If unsure of dimensions then ask LDN Architects. All dimensions are shown in millimetres unless otherwise stated. This is a CAD produced drawing - do **NOT** alter manually. © This Drawing is copyright of LDN Architects LLP