The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re- Inspection*	Description of Works
1	Eil Burn	Station Road beside "Eilburn"	10/08/2016	Remove debris and clear culvert inlet.
				Vegetation and silt build up at culvert inlet/outlet and through culvert to be removed as it is cau
204	Craggan Mill Burn	A95 at Craggen Mill, Grantown-on-Spey	08/06/2016	BEAR informed of works required.
216	Rhives Burn	Ben Braggie car park	18/01/2016	Remove debris and repair the collapsed culvert in the Ben Braggie car park. Landowner conta
222	Ussie Burn	Behind Cottage Bar, Maryburgh	27/11/2015	Branches and debris causing a partial blockage in the burn. Land ownership uncertain
224	Blair of Tarradale Burn	A832 200m west of B9169 junction	15/04/2016	Debris and vegetation to be cleared from culvert inlet.
227		Railway by A830/B8006 junction, Corpach	10/11/2015	Culvert and watercourse leading to culvert to be cleared of vegetation and silt/debris build up.
				Ditch at culvert inlet is overgrown causing partial blockage of the screen. Area immediately up
267	Macrae Grove Burn	To the rear of 12 Macrae Grove	14/07/2015	vegetation removed. Landowner contacted and asked to carry out works.
				Scottish Water sewer outfall headwall is partially collapsed into the watercourse. Headwall to
284	Mill Burn	Opposite 35 Harris Road	22/03/2016	required.
		Adjacent to A834, upstream of St Anne's		
296	Kinellan Burn	Episcopal Church	28/11/2015	New screen arrangement to be designed and installed at culvert inlet to replace existing dama
330	Ault na Skiah	Upper Slackbuie	03/11/2015	Woody debris to be removed from screen which is 80% blinded. Gravel deposits to be cleared
332	Pitmain Burn	A86, Kingussie	14/10/2015	Culvert inlet and outlet partially blocked with sediment and cobbles. BEAR informed of works r
343	Eil Burn	Conon Bridge	09/01/2016	Clear watercourse of sediment and debris for 10m upstream of screen
354	Lochalsh Burn 5	Kyle of Lochalsh	26/10/2015	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping
367	SWFRC	Essich Road	29/06/2015	Trash screen partially blinded. Clear and remove material from site.
373	Tower Burn	Cranmore Drive	10/06/2015	Suspected debris from tree clearance work left in burn causing blockage risk. Remove from Bu
383	Brown Terrace Burn	Kinlochleven	09/08/2015	Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (cons
388	Druid Temple Burn	Drakies Playing Field, Grebe Avenue.	24/06/2015	Fallen tree lying within the watercourse causing a partial blockage. Remove tree and trapped of
394	River Peffery	Between Tulloch Street and railway bridge	12/07/2015	Uprooted trees washed up on bank. Cut into smaller sections to allow them to pass downstrea
395	Essich Burn	Torbreck/Ness Castle	29/09/2015	Stones and rubble blocking one inlet to a double culvert. Landowner contacted and requested
399	Tain Burn 2	Behind Rowan Drive and Hawthorn Way	25/08/2015	Area Team to remove all debris from the length of the between St Vincent and the Inlet of Stru
403	Kylintra Burn	Culverts at the entrance to Woodburn Crescent	09/12/2015	Remove silt deposition which is restricting forward water flow from the culverts.
		Open section of watercourse at Ord Wood, Muir	•	
406	Ord Loch	of Ord	15/09/2015	Clearance of trees and vegetation from the drain to aid conveyance.
		Culvert inlet near to the Ben Wyvis Hotel		Clear debris from the inlet and clear 10m upstream of the culvert inlet, clear the outlet of the cu
412	Ardival Burn	service entrance	30/09/2015	out the works.

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out

ausing a partial blockage and potential flood risk.

tacted and asked to carry out works.

p. Network Rail informed of works required. upstream of screen to be cut back and dead

to be repaired. Scottish Water informed of works

naged screen.

red from upstream side of screen also. s required

g upstream. Land ownership uncertain.

Burn. Passed to SSE.

instructed) bed level from the culvert outlet.

d debris from the watercourse.

eam without snagging ed to remove blockage.

tructure 60.

culvert. Landowner contacted and asked to carry