The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re- Inspection*	Description of Works
		Adjacent to A834, upstream of St Anne's		
296	Kinellan Burn	Episcopal Church	01/01/2017	New screen arrangement to be designed and installed at culvert inlet to replace existing damage
354	Lochalsh Burn 5	Kyle of Lochalsh	10/04/2017	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping
454	Clachan Burn	Bettyhill	01/07/2017	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
		Screen near to the A9 and the screen at Tesco		
461a	Dell Burn	Inches.	30/01/2017	Remove debris from screen locations on the Dell Burn
461b	Ault na Skiah	Screen at 144 Culduthel Road inverness	30/01/2017	Remove debris from screen.
462	Ault na Skiah	Castle Heather Park by B8082	30/01/2017	Silt trap is full and requires material to be removed.
				Upstream of the screen the bank is scouring away, place rock armour or gabion baskets in the
		Screen between Miller Road and the Southern		the screen. Looking downstream from the screen, on the left hand sidewall, voids are forming;
469	Parks Farm Burn	Distributer Road	02/12/2016	and regrouting any cracks.
				Remove all discarded vegetation and debris which has been cast aside from the screen at Shr
470	Abbots Place Burn	End of East Street, Beauly	03/12/2016	top screen to reduce blinding of the top screen. Partially Complete.
		Behind 3 Carn Elrig and between 19 & 20		
480	High Burnside Burn	Patterson Lane	21/12/2016	Remove all silt, stones and vegetation from the culvert outlets
484	Knockbain Burn	Burn Place to Gladstone Avenue	14/02/2017	Jetting required to clear silt build up in culvert.
Í		Foreshore of the River Ness between the		
494	River Ness	junction of Dunabban Road and huntly Place.	09/12/2016	Remove silt and stones which have accumulated at the outlet of the flap valve
495	River Ness	Foreshore of the River Ness.	09/12/2016	Repair broken flap valve.
		Foreshore of the River Ness. Upstream side of		
		the dual carriageway near to the steps which		
496	River Ness	lead down to the footpath.	11/12/2016	Release jammed hinges on the flap valve
		Foreshore of the River Ness. Opposite John		
497	River Ness	Clark House	11/12/2016	Release seized hinges on the flap valve
		Between West Heather Road and Culduthel		Ditching of watercourse channel required where sediment and vegetation has built up to such a
498	Slackbuie Channel	Road	14/02/2017	hand bank.
499	Brown Terrace Burn	Kinlochleven	17/12/2016	Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (cons
				Clear excessive amounts of vegetation from the Pond Burn watercourse, starting from the outle
500	Pond Burn	Carrbridge Primary School Car Park	24/12/2016	from the outlet of the culvert at the fire station.
501	Ussie Burn	Burn behind Hood Street Maryburgh	29/12/2016	Remove large tree which is lying in the watercourse.
502	Not Allocated	Insh House, Loch Insh	17/05/2017	Trial holes have located route of stone culvert. Blockage located along section between culver

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out

naged screen.

g upstream. Land ownership uncertain.

he area of scouring and reform the bank to the top of g; these should be repaired by infilling with concrete

Shrewsbury House. Remove every 2nd bar from the

ch an extent that flow is at risk of overtopping the left

nstructed) bed level from the culvert outlet. utlet of main road culvert to 10metres downstream

vert inlet and point approximately 20m downstream