Works Number	Watercourse Name	Location	Date for Re- Inspection*	Description of Works
	South Kessock			
580 626	Seawall	3 Areas in the seawall	20/01/2026	Repair missing stones sets in the seawall
626	Mill Burn	Culvert under Sir Walter Scott Drive	08/09/2025	Remove all silt and stone deposation from the inlet and ditch 10m upstream from the inlet
		Adjacent to the Distributor Road (B8082) behind		remove silt accumulations from the culvert inlet which has reduced the culvert width by approx
635	Ault na Skiah	properties on Castle Heather Avenue	10/06/2025	growing in the burn or on the burn sides.
635 636	SWFRC	SWRFC numerous locations	03/09/2025	Remove all vegetation gorse/whin are growing on the crown and sides of the flood relief channel
				Silt accumulations and a build up of debris/rubbish at the culvert, some of which is lying at the tw
658	Slackbuie Channel	Junction of Culduthel Road and Green Drive	10/06/2025	possible and ensure inlets are clear.
				The culvert outlet is 50% surcharged due to windblown trees and woody debris lying across the
664	Ault na Skiah	Culvert outlet opposite Evan Barron Rd	08/09/2025	down to the boundary fence of the property. Clear all woody debris from the open section.
724	Knockbain Burn	Knockbain Burn, near Gorstan, Dingwall	02/06/2025	Build up of Silt on LHS near Screen - Should be cleared
		Underneath Bridge on B862, near Holm Lodge.		
738	Holm Burn	Inverness	08/09/2025	Tree Limb stuck underneath Bridge on B862. Limb will need to be removed.
				Partial blockage and likely collapse of stone culvert within 2m of Manhole. Section is estimated
741	Park Burn	Park Road,Sstrathpeffer	07/08/2025	blockage removed.
743	Guisach Burn	Treasures of the Earth Museum	28/05/2025	Screen blinded by sediment. BEAR contacted to clear the screen.
744	Mill Burn	Section between Mason Road & Teal Avenue	10/06/2025	Fallen Trees lying within the Watercourse accumulating Derbis. Trees & Debris to be removed t
		Culvert under single track road near Am Bothan,		
748	Gergask Burn	Laggan	06/08/2025	Culvert Inlet blocked with Wooden debris & Large Tree Branch, should be removed to ensure u
		Screened Inlet to Culvert under Station Road		Inlet area silted up which has raised the bed of the watercourse, silting the Screen Inlet by appro
749	Eil Burn	(A862), Conon Bridge	31/07/2025	Inlet.
751	Culloden Burn West	Outlet of Culvert, next to Gruffalo carving	09/09/2025	Burn blocked with cluster of Woody debris, should be cleared to ensure un-restricted flow
		Within Farm field east of St Trothan's Church,		Multiple fallen trees & concrete slabs lying within Burn D/S from Outlet, this should be cleared to
754	Olrig Cemetery Burn	Olrig Cemetery, Castletown	18/08/2025	issued
758	Culloden Burn West	Ferntower Avenue	15/08/2029	Jetting required to clear debris in culvert.
		Upper Slackbuie, near Electricity Distribution		
766	Ault Na Skiah	Site, Inverness	02/06/2025	Screen 50% blocked with washed down stones & debris. Screen to be cleared.
				Significant amount of litter/ rubbish surrouding the watercourses of Slackbuie Spring & Channel
769	Slackbuie Spring	ASDA Superstore, Slackbuie, Inverness	10/06/2025	S18 Letter to have rubbish, veg & debris removed.
771	Smithton Burn	Woodside Village, Westhill, Inverness	11/06/2025	Rubbish & dumpings by Inlet area, S18 Letter issued to remove
773	Avoch Burn	Upstream from FB near Primary School	11/08/2025	Trees/ limbs have either snapped/ fallen into the burn. Trees should be removed
774	Bridge of Winless	Bridge Of Winless, Winless, Wick	18/08/2025	Piped Inlets on LHS & RHS of Bridge silted, should be ditched out to ensure unrestricted waterf
	Caol Lochyside Flood			
775	Defences	Duck Billed Flap Valve within Section 3. Caol	25/06/2025	Duck Billed FV 50% surcharged with stones, stones should be removed from Outlet area
776	Alton Burn	3 Muircote Rd, Nairn	19/11/2025	Corrugated Iron Sheets from LHS wall lying in Watercourse, restricting waterflow. Should be re-
		Section of burn between Glenshian & Alt na		
777	Allt na Churra	Churra	26/11/2025	Garden clippings dimped in burn - Section 18 Letter sent

\* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out

x 50%, please remove any self seeded trees that are

nel. Currently growing is numerous areas twin culvert inlets, please remove as much silt as

he watercourse for the majority of the open section

ed to be below footpath. Callapse to be repaired and

d to ensure un-restricted flow.

e un-restricted flow

prox. 50%. Silt should be removed surrounding the

to ensure un-restricted waterflow. Section 18 letter

nel, overgrown with debris blocking Inlet of culvert.

erflow.

re-installed/ replaced Section 18 Letter sent