


EAST ELEVATION



Stone New stone tooled and sized to match existing Lime mortar beds to match existing

(P8)

31-35 MARCHMONT ROAD EDINBURGH EH9 1 HU

01/02. GASTROPUB / STONECUTTER'S

16.07.20 material clarification

notes

989-TON-P-01-**302** Rev: A

3. Any discrepancies to be reported to Architect.

drawings, specifications and schedules. 5. Location of stud in partitions are indicative only.

ELEVATIONS EAST and NORTH

Do not scale from drawings. Request from Architect any dimensions not provided.
All dimensions to be checked on site prior to starting work.

1:50 @ A1, 1:100 @ A3

4. Drawings to be read in conjunction with structural engineer's and consultant's

helen lucas ARCHITECTS

mail@helenlucas.co.uk

TONGUE GARAGE

t0|3| 478 8880

AS PROPOSED


PLANNING NOT FOR CONSTRUCTION


revision

date

scale bar - 1:50 0 I 2 2.5m KEYS Existing building New structures Demolitions (P2)

-----





SECTION B-B Bakehouse Elevation (South)

scale bar - 1:50 0 I 2 2.5m

KEYS



Existing building New structures

#### MATERIALS LEGEND

EXISTING MA	TERIALS
	<b>Timber Cladding</b> Existing timber cladding removed, reconditioned and re-installed. Supplemented with new boards to match as necessary.
E2	<b>Brickwork</b> Existing re-pointed with traditional lime mortar, areas of cement mortar raked out. Repaired and replaced where necessary with new brickwork to match / re-use of existing on site as available.
E3	<b>Stonework</b> Existing stone re-pointed with traditional lime mortar to match existing. Existing cement mortar raked out.
E4	Metal Roofing Re-use of the metal profiled roofs where condition permits.
	<b>Slate roofing</b> Recondition existing slate roof, replace areas of broken tiles or deterioration with slate to match existing.
PROPOSED N	1ATERIALS
PI	<b>Timber Cladding</b> Selected to compliment cladding in existing buildings

PI	<b>Timber Cladding</b> Selected to compliment cladding in existing buildings
	Brickwork
P3	Cor-ten steel cladding
(P4)	<b>Zinc cladding</b> Finish: Pre-weathered Grey
P5	Slate roofing
P6	Timber-framed windows and doors
P7	Metal-framed windows and doors
P8	<b>Stone</b> New stone tooled and sized to match existing Lime mortar beds to match existing
	Rainwater goods



-

-

revision date notes

P9 Rainwater goods Grey metal to match existing / new roof coverings



-

# helen lucas ARCHITECTS

mail@helenlucas.co.uk 31-35 MARCHMONT ROAD EDINBURGH EH9 1 HU

t0|3| 478 8880

TONGUE GARAGE

01/02. GASTROPUB / STONECUTTER'S

Do not scale from drawings. Request from Architect any dimensions not provided.
All dimensions to be checked on site prior to starting work.

4. Drawings to be read in conjunction with structural engineer's and consultant's

AS PROPOSED

SECTION A-A B-B

989-TON-P-01-**303** Rev: --


1:50 @ AI, 1:100 @ A3

3. Any discrepancies to be reported to Architect.

drawings, specifications and schedules. 5. Location of stud in partitions are indicative only.



SECTION CC



SECTION DD

revision date note

PLANNING NOT FOR CONSTRUCTION

# helen lucas ARCHITECTS


elenlucas.co.uk 31-35 MARCHMONT ROAD EDINBURGH EH9 IHU t0|3| 478 8880

TONGUE GARAGE 01/02. GASTROPUB / STONECUTTER'S AS PROPOSED SECTIONS C-C / D-D

989-TON-P-01-350 Rev:--

1:50 @AI, 1:100 @A3

Do not scale from drawings. Request from Architect any dimensions not provided.
All dimensions to be checked on site prior to star ting work.
Any discrepancies to be report ted to Architect.
Drawings to be read in conjunction with structural engineer's and consultant's drawings, specifications and schedules.
Location of stud in par titions are indicative only.



SECTION EE

Drawings to be read in conjunction with structural engineer's and consultant's drawings, specifications and schedules.
Location of stud in partitions are indicative only.

Do not scale from drawings. Request from Architect any dimensions not provided.
All dimensions to be checked on site prior to starting work.
Any discrepancies to be reported to Architect.

## I:50 @ AI, I:100 @ A3

# 989-TON-P-01-**351** Rev: --

## AS PROPOSED SECTION E-E

01/02. GASTROPUB / STONECUTTER'S

TONGUE GARAGE


mail@helenlucas.co.uk 31-35 MARCHMONT ROAD EDINBURGH EH9 1 HU t0|3| 478 8880

helen lucas ARCHITECTS

## PLANNING NOT FOR CONSTRUCTION

revision date notes

- - -



Existing building New structures


scale bar - 1:50 0 I 2 2.5m






PROPOSED ROOF PLAN

r------













NOT FOR CONSTRUCTION helen lucas ARCHITECTS mail@helenlucas.co.uk 31-35 MARCHMONT ROAD EDINBURGH EH9 IHU t0131 478 8880 TONGUE GARAGE SITE 08. SITE OPERATIONS AS PROPOSED FLOOR PLANS 989-TON-P-08- 201 Rev: --


notes


date

PLANNING

revision

Do not scale from drawings. Request from Architect any dimensions not provided.
All dimensions to be checked on site prior to starting work.
Any discrepancies to be reported to Architect.
Drawings to be read in conjunction with structural engineer's and consultant's drawings, specifications and schedules.
Location of stud in partitions are indicative only.





scale ba	ar - 1:50				
0	I		2	-	2.5m
© Helen L	ucas Archited	ts Ltd.	Compan	ıy l	No. SC522478

#### KEYS

Existing building

New structures Demolitions 

MATERIALS LEGEND

## EXISTING MATERIALS

(EI)	
(E2)	

 
 EI
 Timber Cladding

 Existing timber cladding removed, reconditioned and

 re-installed. Supplemented with new boards to match as
 necessary.

Brickwork

Existing re-pointed with traditional lime mortar, areas of cement mortar raked out. Repaired and replaced where necessary with new brickwork to match / re-use of existing on site as available.



#### Stonework

E3 Stonework Existing stone re-pointed with traditional lime mortar to match existing. Existing cement mortar raked out.



#### Metal Roofing Re-use of the metal profiled roofs where condition permits.

of broken tiles

E5)	Recondition existing slate roof, replace areas of broken or deterioration with slate to match existing.
PROPOSED N	1ATERIALS
PI	<b>Timber Cladding</b> Selected to compliment cladding in existing buildings
· · P2 · ·	Brickwork
P3	Cor-ten steel cladding
P4)	<b>Zinc cladding</b> Finish: Pre-weathered Grey
P5	Slate roofing
P6	Timber-framed windows and doors
P7	Metal-framed windows and doors
(P8)	<b>Stone</b> New stone tooled and sized to match existing Lime mortar beds to match existing
P9	<b>Rainwater goods</b> Grey metal to match existing / new roof coverings

-

-

notes

PLANNING NOT FOR CONSTRUCTION

# helen lucas ARCHITECTS

mail@helenlucas.co.uk

31-35 MARCHMONT ROAD EDINBURGH EH9 1 HU t0|3| 478 8880

TONGUE GARAGE SITE

08. SITE OPERATIONS

AS PROPOSED

ELEVATIONS

989-TON-P-08- 301 Rev: --

1:50 @ A I

Do not scale from drawings. Request from Architect any dimensions not provided.
All dimensions to be checked on site prior to starting work.

- 3. Any discrepancies to be reported to Architect. 4. Drawings to be read in conjunction with structural engineer's and consultant's

drawings, specifications and schedules. 5. Location of stud in partitions are indicative only.



scale ba	ar - 1:50		
0		2	2.5m
© Helen l	Lucas Architects Ltd.	Company	No. SC522478

KEYS



Existing building New structures Demolitions



revision date notes

PLANNING NOT FOR CONSTRUCTION

helen lucas ARCHITECTS

mail@helenlucas.co.uk

31-35 MARCHMONT ROAD EDINBURGH EH9 1HU t 0131 478 8880

TONGUE GARAGE SITE


08. SITE OPERATIONS AS PROPOSED

SECTION AA

989-TON-P-08-**350** Rev:--

1:50 @ A3

Do not scale from drawings. Request from Architect any dimensions not provided.
2.Al dimensions to be checked on site prior to starting work.
3.Any discrepancies to be reparted to Architect.
4. Drawings to be read in conjunction with tructural engineer's and consultant's drawings; specifications and schedules.
5. Location of stud in partitions are indicative only.



helen lucas ARCHITECTS

31-35 MARCHMONT ROAD EDINBURGH EH9 1 HU

Do not scale from drawings. Request from Architect any dimensions not provided.
All dimensions to be checked on site prior to starting work.
Any discrepancies to be reported to Architect.
Drawings to be read in conjunction with structural engineer's and consultant's drawings, specifications and schedules.
Location of stud in partitions are indicative only.

989-TON-P-09**-201** Rev: --

- - revision date notes

PLANNING

NOT FOR CONSTRUCTION

mail@helenlucas.co.uk

TONGUE GARAGE SITE

1:50 @ A1; 1:100 @ A3

t0|3| 478 8880

AS PROPOSED -

shop: plans

09. SHOP


scale bar - 1:50 0 I 2 2.5m

Demolitions

Existing building New structures

KEYS -----


2 2.5m




EAST ELEVATION



WEST ELEVATION







SOUTH ELEVATION

scale bar - 1:5	
0	I 2 2.5m
KEYS	
	Evipting building
	Existing building New structures
<i></i>	Demolitions
MATERIALS L	EGEND
EXISTING M/	ATERIALS
	Timber Cladding
EI	Existing timber cladding removed, reconditioned and re-installed. Supplemented with new boards to match as necessary.
(F2)	Brickwork
	Existing re-pointed with traditional lime mortar, areas of cement mortar raked out.
	Repaired and replaced where necessary with new brickwork to match / re-use of existing on site as available.
	Stonework
(E3)	Existing stone re-pointed with traditional lime mortar to
	match existing. Existing cement mortar raked out.
E4	Metal Roofing Re-use of the metal profiled roofs where condition permits.
E5LL	Slate roofing Recondition existing slate roof, replace areas of broken tiles
	or deterioration with slate to match existing.
PROPOSED 1	MATERIALS
PD	Timber Cladding
PI	Selected to compliment cladding in existing buildings
	Brickwork
P2 '	DICKWOIK
	Cor-ten steel cladding
(P3)	C C
	Zinc cladding
(P4)	Finish: Pre-weathered Grey
(P5)	Slate roofing
	Timber-framed windows and doors
(P6)	Timber-framed windows and doors





### revision date notes

-

-

PII

P8 Stone New stone tooled and sized to match existing Lime mortar beds to match existing

Grey metal to match existing / new roof coverings

-

# PLANNING

Rainwater goods Grey metal +-

Profiled metal roof

NOT FOR CONSTRUCTION

# helen lucas ARCHITECTS

mail@helenlucas.co.uk

31-35 MARCHMONT ROAD EDINBURGH EH9 1 HU t0|3| 478 8880

TONGUE GARAGE SITE

09. SHOP

AS PROPOSED -

SHOP: ELEVATIONS

989-TON-P-09**301** 


1:50 @ AI; 1:100 @ A3


Rev: --

Do not scale from drawings. Request from Architect any dimensions not provided.
All dimensions to be checked on site prior to starting work.
Any discrepancies to be reported to Architect.
Drawings to be read in conjunction with structural engineer's and consultant's drawings, specifications and schedules.
Location of stud in partitions are indicative only.




			A Drainage Layout revised. YM FM 29.10.19   Rev Description By Date   Status PLANNING
	40.0 Marine Marine Marine Marine Marine Mari		david narro associates     Consulting Structural & Civil Engineers     34-36 Argyle Place, Edinburgh, Eth9 1JT T 0131 229 5533 F 0131 229 5090 W http://www.davidnarro.co.uk E mail@davidnarro.co.uk     24 James Morrison Street, Glasgow, G1 5PE T 0141 552 6080 F 0141 552 6080 F 0141 552 7418 W http://www.davidnarro.co.uk E mail@davidnarro.co.uk     Client     KRAMER & CO     Architect     HELEN LUCAS ARCHITECTS     Job Title
			TONGUE GARAGE, TONGUE     Sheet Title     DRAINAGE LAYOUT     Drawn   Designed   Checked     GG   YM   LPH     Scale   Date   OCT 2019     Drawing No.   Revision     18.1142-700   C






# Section locator 1:100



Project:	TONGUE GARAGE
Client	WILDLAND LTD
Drawing:	Sections Re-opened Burn/Drainage Ditch
<b>Drawing Nr:</b>	1908.L.L.(93)001
Rev:	-
Date:	21.02.20
Status:	Planning Application
Scale:	1:250/100/50

UrbanPioneers Landscape Architects 3 Tweeddale Court, 14 High Street, Edinburgh EH1 1TE liane@urbanpioneers.co.uk



# Proposed Tree removal 1:1000

Proportion of tree removal (red) to tree retention (black)

Overall proposed removal 75 trees of these: Category A: 3 Category B: 45 Category C: 21 Category U: 6

25nr of Category B 45nr trees are of fair rather than good condition (20nr)

**Tree retained 41 Trees** of these: Category A: 6 Category B 30 Category C 6

Refer to drawing 0903.L.G.(92)004 for planting plan We propose to plan 89 new trees

NR	SPECIES	GORY	CONDITI ON	AGE	COMMENTS ARBORICULTURIST	REASON FOR REMOVAL
3155	Silver Birch	U	Dying	E-M		Dying
3156	Silber Birch	C1	Poor	E-M	Low vigor, poor shoot extension, thin	Poor condition
3157 Group	Sitka Spruce	B2	Good	M-A	foliage. Heavily shaded and 1-sided Group Sitka Spruce	Blocking view, intension is to open up some views
						and interplants with broadleaves to integrate better into surrounding landscape
3162	Silver Birch	B1	Good	E-M		To allow adjacent Beech to developm more uniform/balanced crown
3163	Sycamore	B1	Fair	E-M	Canopy one-side	Take down to benefit Tree 3165
3164 3166	Sycamore	B1 C1	Fair Poor	E-M M-A	Canopy one-side	Take down to benefit Tree 3165 Poor condition
3100	Cherry Gean		Poor	IVI-A	Canopy surpressed. One stem of two dead. Reminder biased to E	Poor condition
3167	Sycamore	B1	Fair	M-A	Branches affecting adjacent structure. Against shed, branches on roof	May need to be removed to accommodated demolition and new building
3168	Sycamore	B1	Fair	E-M	Minor stem wound from fence wire	May need to be removed to accommodated demolition and new building
3141	Ash	C1	Fair	Y	Restricted rooting due to ground conditions. Small growing, on wall against tin shed. Potentially remove as	Clashes with proposed building footprint, Change in level
3142	Sycamore	C1	Fair	E-M	part of development works Coppice regrowth. Grows on wall against shed. Potentially rmeove as part of development works	Clashes with proposed building footpring. Also shed against which is grows is to be removed
3143	Sycamore	B1	Good	E-M	Branches affecting adjacent BT poles and cables	Tip back secondary branch growth to remove confilict with adjacent pole/cables
3144	Rowan	B1	Good	M	In garden of Dalvarich Lodge	
3145	Rowan	U	dead			
3140	Sycamore	B1	Good	E-M	Branches affecting adjacent BT pole and cables	To be removed due to required change in levels ensuring Village Square is accessible
3147	Sycamore	A1	Good	E-M	On boundary to field	
3148	Sycamore	A1	Good	E-M	On boundary to field	
3149 3173	Sycamore Beech	A1 C1	Good Fair	E-M M	On boundary to field Significant cavity/decay in stem at 5m.	Take out for longterm Health and Safety
					Weak fork at 3m. Old break-out wound will eventually fail. Monitor decay at regular intervals	The out for forgram meaning and salety
3174	Sycamore	B1	Good	M-A	Deformed stem, otherwise good	Removal proposed due to required adjustments to surrounding levels
3139	Sycamore	C1	Fair	E-M	Self-seeded, grows through chain link fence. Concrete plinth to E. Close to BT pole. Potentially remove as part of redevelopment works	Removal proposed due to required adjustments to surrounding levels, installation of road/parking bays
3179	Sycamore	B1	Fair	M-A	Regrown from decayed stump	Change in level required
NO NR	Collapsed Sycamore				Collpasing split Sycamore, leans over bridge	Removed to protect bridge
3183	Beech	C1	Poor	M-A	Restricted rooting due to ground conditions. Coppice re-growth. Multiple stems from gl, grows on bank adjacent to retaining wall. Potentially remove as part of redevelopment	Removals proposed due to poor condition and required change in levels
3184 Group	Group of 4 Sycamore	C1	Poor	E-M	Group of 4, all topped, multi-stem, growing along bank between building and cottage. Potentially remove as part of redevelopment	Removals proposed due to poor condition and required change in levels
3185	Elm	C1	Fair	Y	At end of Sycamore group. Previously topped. Potentially remove as part of redevelopment works	Removal proposed due to poor condition and required change in levels
3186	Ash	C1	Fair	E-M	Coppice regrowth	Removal proposed due to poor condition and
3187	Sitka Spruce	B1	Good	M-A		required change in levels Removal proposed due to required change in levels
3188	Elm	B1	Fair	M-A	3 stems form gl	Removal proposed due to required change in levels
3189	Elm	C1	Fair	M-A	Coppice regrowth. Multiple stems with significant epicormic growth	Removal proposed due to poor condition and required change in levels
3190 Group	Sycamore	C1	Fair	Y	Group fo 7 stems, all small	Removal proposed due to poor condition and
3200	Sucamora	C1	Fair	E-M	Coppice regrowth. From old decayed	required change in levels Removal proposed due to poor condition and
	Sycamore				stump. 2 further small stems forming group	required change in levels
3192 Group	Sitka Spruce	3nr U 1nr C1 16nr B	Fair	M-A	Two Stems previously topped , crown regrown with multiple leaders. Start of row around perimeter, trees up to 23m height	Removal proposed due to poor condition and required change in levels
3191	Ash	B1	Fair	M	Low vigour, poor shoot extension, thin foliage. Minor crown dieback. Monitor	Removal proposed due to poor condition and required change in levels
3193	Elm	C1	Fair	M	Significant cavity/decay in stem. Stem appears hollow, some obvious decay between buttresses, but no obvious open cavaties. Monitor decay at regular intervals. May need to make safe if	Removal proposed due to poor condition and required change in levels
3195 Group	Sycamore	B1	Good	E-M	target introduced Scattered group of 6 y to e-m scamore adjacent to group of spruce demarcating boundary	Removal proposed due to required change in levels
3194	Ash	C1	Poor	М	Low vigour, poor shoot extension, thin foliage. Minor crown dieback. Montior annually	Removal propose due to poor condition
3195 Group	Sycamore	B1	Good	E-M	Scattered group of y to e-m Sycamore adjacent to group of spruce demarcating boundary	Removal due to change in level
3196	Elm	B1	Fair	M-A	Coppice regrowth	Removal proposed to installed required parking/tracking
3197	Sycamore	B1	Fair	M-A	Coppice regrowth, 11 stems x 25cm	Removal proposed to installed required
3199	Elm	B1	Fair	E-M	Topped at 5m. Crown regrown from 5m.	parking/tracking Removal proposed to installed required
3198	Elm	B1	Fair	E-M	Overhead cable adjacent Coppice regrowth. 3 main stems from coppice stool, each 30dbh, plus established stem from sucker, 30cm.	parking/tracking Removal proposed to installed required parking/tracking
					Dense epicormic growth from base	
G3192	Sitka Spruce	C1	Fair	М	Two stems previously topped, crown regrown with mulitple leaders. Start of row around perimeter, trees up to 23m height	Removal proposed for benefit of three 3195 and to be replaced with broadleave species which are more in keeping with overall character of landscape and allow views in and out/assist with visibility

UrbanPioneers Landscape Architects 3 Tweeddale Court, 14 High Street, Edinburgh EH1 1TE liane@urbanpioneers.co.uk

24.02.2020	
16.07.2019	

Client

Rev:

Date:

Status:

Scale:

REV B: Switched on site boundary REV A: Added 8nr trees to removal

Project: TONGUE GARAGE

**Drawing:** Tree removal plan

Drawing Nr: 1908.L.G.(92)002

26.05.2019

Information

1:300/1000

В

WILDLAND LTD

o change in level
sed to installed required g







Small ornamental trees/shurbs to provide seasonal interest 25nr Mixed species (Snowy mespilus, Rowan, Magnolia) Extra heavy standard, wide spacing

Rowan: 14-16cm girth rootballed, full evenly branched Crown with single strong leader true to type, 200cm clear stem, 500cm overall height. Snowy mespilus: Multistem, 4xtr, Spread 150-200cm, Height 300-350cm Magnolia: Multistem, 6xtr, Spread 200-300cm, Height 300-350cm

2000x2000x750mm pit filled with 50% imported topsoil and 50% tree planting compost.

Tree pit drainage connected to local drainage trench. Allow for root barriers when planted adjacent to u/g services. Tree pit to contain aeration pipe. Underground guyed.

Top soil to be Multi Purpose in accordance with 'BS 3882-2015 Topsoil'. Sub soil to be Multipurpose topsoil in accordance with 'BS 8601-2013

Specification for subsoil and requirements for use'.

Minimum combined depth of topsoil and subsoil to be 900mm

Beech (Fagus sylvatica) Hedging plants, 2xtr, rootballed, 150-175cm

300mm depth imported topsoil over clean ripped subsoil. Cultivate and add compost, plant double staggered rows of 150-175m high feathered transplants at 7 per lin. m. 50mm depth composted bark mulch finish for full width between kerbs. 1100mm high timber post and strained wire fencing along centre of hedge. Top soil to be Multipurpose Grade in accordance with 'BS 3882-2015 Topsoil'. Subsoil to be Multipurpose Grade in accordance with 'BS 8601-2013 Specification for subsoil and requirements for use'.

Minimum combined depth of topsoil and subsoil to be 600mm

### All Herbeceuous planting/understorev

300mm depth approved imported topsoil over clean, ripped subsoil. Cultivate, adding compost, and plant with 3 litre pot grown plants at 9/m2. 50mm depth composted bark mulch finish. Grasses to be in accordance with BS 3936 Part 1:1992, and shall be planted to BS 4043:1989. Top soil to be Multipurpose Grade in accordance with 'BS 3882-2015 Topsoil'. Sub soil to be Multipurpose Grade in accordance with 'BS 8601-2013 Specification for subsoil and requirements for use'.

Minimum combined depth of topsoil and subsoil to be 600mm

Tree Walk a reptans 'Alba' n neapolitanum 'Cowanii ' divaricatus enia 'Ice Queen' nium macrorrhizum 'Album' a sylvatica 'Marginata' tichum polyblepharum Ila sieboldii L cameos	Indicative Percentage 20.00% N/A* 10.00% 15.00% 20.00% 5.00% 20.00% 100.00%	
dland Planting aurea montana orbia palustris birica anthemum vulgare caria officinalis tichum polyblepharum ula veris ctrum aquilegifolium 'Album' NL ent of mix - planted with wide spacir	Indicative Percentage* 10.00% 15.00% 20.00% 15.00% 5.00% 15.00% 5.00% 100.00% ng into grassland	
a <b>Courtyards</b> atherum calamagrostis n 'Purple Sensation' n sphaerocephalon nagrostis 'Karl Foerster' alaria gigantea ndula rubra 'Venusta' nium 'Patricia' nium 'Patricia' nium 'Orion' n 'Mrs Bradshaw' tia macedonica n tigrinum 'Splendens' nis chalcedonica ia 'Transparent' caria 'Betty Brandt' caria 'Betty Brandt' caria 'Early Bird' pys 'Hummelo' nicastrum 'Erica' AL cameos	Indicative Percentage 10.00% N/A* N/A* 3.00% 5.00% 5.00% 7.00% 10.00% 5.00% 10.00% 3.00% 7.00% 5.00% 5.00% 5.00% 10.00% 5.00% 10.00%	
ered Courtyard ea ptarmica banula persicifolia lophium denudatum ranthus ruber rophyllum hirsutum 'Roseum' bsmia masoniorum 'Rowallana' hampsia 'Schottland' ndula rubra 'Venusta' nium 'Orion' um 'Blush' ula sieboldii uisorba officinalis tria autumnalis tria autumnalis sa pratensis iana officinalis subsp. sambucifolia	Indicative Percentage 7.00% 6.00% 5.00% 5.00% 5.00% 7.00% 10.00% 3.00% 10.00% 5.00% 5.00% 5.00% 5.00% 10.00% 7.00% 3.00% 100.00%	
y areas behind restaurant can also be used as kitchen garden		
24 02	.2020 REV B: Switched on sit	


REV B: Switched on site boundary, Added explanation to Visibility Splay

Project:	TONGUE GARAGE
Client	WILDLAND LTD
Drawing:	Planting plan
<b>Drawing Nr:</b>	1908.L.G.(92)003
Rev:	A
Date:	14.10.2019
Status:	Information
Scale:	1:300


24.02.2020


20m

**UrbanPioneers Landscape Architects** 3 Tweeddale Court, 14 High Street, Edinburgh EH1 1TE liane@urbanpioneers.co.uk









Tree protection fence in line with figure 2, BS5837-2012 to protect trees from impact of Construction

Tree protection measures i such as ground protection, hand digging and trenchless solutions in line with BS5837-2012 where works within Root protection areas are unavoidable

Motorhome Discharging Point and Fresh Water Connection

Motorbike Motorbike

Motorbike

G319

N

 $\land$ 

Similar to tree 3165 with aim to retain tree 3146 if at all possible (Lodgepole pine, A1, good condition.

## Proposed measures:

Styeochin sig decay in lower


3180

Shed limit recently M elm in adjacent grnd.

3182

曰

000



8


Key 4 Ground level

scale bar - 1:300

15

20m

0 2 4 6 8 10



24.02.2020

REV B: Switched on site boundary

TONGUE GARAGE Project: Client WILDLAND LTD **Drawing:** Tree protection plan Drawing Nr: 1908.L.G.(92)003 Rev: Α Date: Status: 1:300 Scale:

14.10.2019 Information

UrbanPioneers Landscape Architects 3 Tweeddale Court, 14 High Street, Edinburgh EH1 1TE liane@urbanpioneers.co.uk

