The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re- Inspection*	Description of Works
		Adjacent to A834, upstream of St Anne's		
296	Kinellan Burn	Episcopal Church	06/01/2019	New screen arrangement to be designed and installed at culvert inlet to replace existing damage
354	Lochalsh Burn 5	Kyle of Lochalsh	24/03/2019	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping up
454	Clachan Burn	Bettyhill	22/08/2019	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
462	Ault na Skiah	Castle Heather Park by B8082	07/01/2019	Silt trap is full and requires material to be removed.
		A870 at the junction with Auchingale Place		The Invert levels of the ditch have risen due to vegetation and silt deposition. Return ditch to orig
529	Knightswood Burn	Watten.	21/08/2019	roads.
532	Lochalsh Burn 4	Church Street, Kyle of Lochalsh	28/12/2018	Replace section of collapsed stone culvert with 400mm diameter pipe.
				Remove all vegetation and silt and stones which have accumulated in front of the screen, clear t
537	Allt na Laitch	A862 prior to the Mineral Bridge	07/01/2019	will allow any silt which has accumulated within the culvert to wash out
		Outlet of the Parks Farm Burn in to the Druid		
540	Parks Farm Burn	Temple Burn at the Grebe Avenue Hall	11/12/2018	Secure the chain to the screen which has been removed.
549	Scretan Burn Trib 3	Behind 1 Brinkman Terrace	12/03/2019	The culvert is blocked and requires clearing this is not an urgent job as there is an overflow char
				Remove a 10m X 2m area of silt deposition at the outlet of the box culvert which has restricted the
559	Mill Burn	Harris Road Inverness	18/12/2018	vegetation from the culvert inlet upto the footbridge which is opposite Milton Crescent
561	Aul na Skiah	Culduthel Road	18/12/2018	Remove all vegetation set aside during burn clearance
562	Druid Temple Burn	Old Edinburgh Road	18/12/2018	Remove all vegetation in and along both sides of the burn, all vegetation should be removed after
563	Old Manse Burn	Avoch	18/12/2018	Culvert inlet to be cleared. Currently blocked by build up of sediment, clear back upstream to ret
564	Dirty Well	Behind the masonic Lodge, Portree	04/01/2019	Clear the screen behind the Masonic Lodge
L				

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out

ged screen.

upstream. Land ownership uncertain.

riginal invert level to help mitigate flooding on to the

r the culvert outlet to a point 10m downstream this

nannel

the width of the burn, remove areas of minor

fter cutting

return burn to original invert levels