

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
296	Kinellan Burn	Adjacent to A834, upstream of St Anne's Episcopal Church	04/11/2019	New screen arrangement to be designed and installed at culvert inlet to replace existing damaged screen.
354	Lochalsh Burn 5	Kyle of Lochalsh	25/12/2019	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping upstream. Land ownership uncertain.
454	Clachan Burn	Bettyhill	19/08/2020	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
529	Knightswood Burn	A870 at the junction with Auchingale Place Watten.	19/08/2020	The Invert levels of the ditch have risen due to vegetation and silt deposition. Return ditch to original invert level to help mitigate flooding on to the roads.
532	Lochalsh Burn 4	Church Street, Kyle of Lochalsh	25/12/2019	Replace section of collapsed stone culvert with 400mm diameter pipe.
537	Allt na Laitch	A862 prior to the Mineral Bridge	04/11/2019	Remove all vegetation and silt and stones which have accumulated in front of the screen, clear the culvert outlet to a point 10m downstream this will allow any silt which has accumulated within the culvert to wash out
540	Parks Farm Burn	Outlet of the Parks Farm Burn in to the Druid Temple Burn at the Grebe Avenue Hall	05/12/2019	Secure the chain to the screen which has been removed.
549	Scretan Burn Trib 3	Behind 1 Brinkman Terrace	05/12/2019	The culvert is blocked and requires clearing this is not an urgent job as there is an overflow channel
559	Mill Burn	Harris Road Inverness	05/12/2019	Remove a 10m X 2m area of silt deposition at the outlet of the box culvert which has restricted the width of the burn, remove areas of minor vegetation from the culvert inlet upto the footbridge which is opposite Milton Crescent
562	Druid Temple Burn	Old Edinburgh Road	05/12/2019	Remove all vegetation in and along both sides of the burn, all vegetation should be removed after cutting
572	Beechwood Burn	Opposite the Veterinary Centre on the B9006 Culloden Road	05/12/2019	The outlet area of the culvert is suffering silt and vegetation deposition, ditch burn 10 metres downstream from the outlet and return burn to original invert levels.
579	Culduthel Channel	Car Park next to Culduthel Mains Court,	05/12/2019	Culvert is surcharged the outlet is approx 75% surcharged due to deposition, ditch and return the outlet to the original level, Jetting may also be required to ensure there are no blockages/silt deposits with the culvert.
580	South Kessock Seawall	3 Areas in the seawall	05/12/2019	Repair missing stones sets in the seawall
591	Knockbain Burn	Behind D Gunn Funeral Home	25/10/2019	Cut down all self seeded trees growing along the burnsides behind the funeral home.
593	River Peffery	Locations between Roberts Bridge and Peters Bridge	08/01/2020	Remove wind blown trees lying in and over the river peffery at 3 locations

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out