

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
296	Kinellan Burn	Adjacent to A834, upstream of St Anne's Episcopal Church	06/01/2020	New screen arrangement to be designed and installed at culvert inlet to replace existing damaged screen.
354	Lochalsh Burn 5	Kyle of Lochalsh	25/12/2019	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping upstream. Land ownership uncertain.
454	Clachan Burn	Bettyhill	19/08/2020	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
529	Knightswood Burn	A870 at the junction with Auchingale Place Watten.	19/08/2020	The Invert levels of the ditch have risen due to vegetation and silt deposition. Return ditch to original invert level to help mitigate flooding on to the roads.
532	Lochalsh Burn 4	Church Street, Kyle of Lochalsh	25/12/2019	Replace section of collapsed stone culvert with 400mm diameter pipe.
537	Allt na Laitch	A862 prior to the Mineral Bridge	06/01/2020	Remove all vegetation and silt and stones which have accumulated in front of the screen, clear the culvert outlet to a point 10m downstream this will allow any silt which has accumulated within the culvert to wash out
540	Parks Farm Burn	Outlet of the Parks Farm Burn in to the Druid Temple Burn at the Grebe Avenue Hall	04/03/2020	Secure the chain to the screen which has been removed.
549	Scretan Burn Trib 3	Behind 1 Brinkman Terrace	04/03/2020	The culvert is blocked and requires clearing this is not an urgent job as there is an overflow channel
559	Mill Burn	Harris Road Inverness	04/03/2020	Remove a 10m X 2m area of silt deposition at the outlet of the box culvert which has restricted the width of the burn, remove areas of minor vegetation from the culvert inlet upto the footbridge which is opposite Milton Crescent
562	Druid Temple Burn	Old Edinburgh Road	04/03/2020	Remove all vegetation in and along both sides of the burn, all vegetation should be removed after cutting
572	Beechwood Burn	Opposite the Veterinary Centre on the B9006 Culloden Road	04/03/2020	The outlet area of the culvert is suffering silt and vegetation deposition, ditch burn 10 metres downstream from the outlet and return burn to original invert levels.
579	Culduthel Channel	Car Park next to Culduthel Mains Court,	04/03/2020	Culvert is surcharged the outlet is approx 75% surcharged due to deposition, ditch and return the outlet to the original level, Jetting may also be required to ensure there are no blockages/silt deposits with the culvert.
580	South Kessock Seawall	3 Areas in the seawall	04/03/2020	Repair missing stones sets in the seawall
596	Lochardil Burn	Lodge Park	03/01/2020	Remove all vegetation which is blocking the watercourse in the Lodge Park area.
597	Dell Burn	Golden Bridge and Inches	06/01/2020	All debris cast aside from screen clearing to be removed from site, the area prior to the screen at Tesco inches requires removal of all vegetation which has accumulated in the watercourse.
598	Slackbuie Channel	SWRFC interface at Upper Slackbuie	06/01/2020	Remove all vegetation and silt which has accumulated within the inlet area to allow normal water levels to flow down the burn.
599	Tower Burn	Caulfield Road North	03/01/2020	Remove all of the debris caught on the screen and the debris and silt accumulated just upstream.
600	Culloden Burn West	Behind the Culloden Centre	03/03/2020	Small area of silt and stones just upstream of the screen requires removal.
601	Mill Burn	Downstream of Diriebught House	03/01/2020	Clear all vegetation growing into and over the burn, from Diriebught House downstream up to a point opposite the small dwarf wall
602	Mill Burn	Premier Inn Car Park	03/03/2020	Remove all silt, stones and vegetation from the short open section

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out