The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re- Inspection*	Description of Works
Number		Adjacent to A834, upstream of St Anne's		
296	Kinellan Burn	Episcopal Church	02/03/2020	New screen arrangement to be designed and installed at culvert inlet to replace existing damage
354	Lochalsh Burn 5	Kyle of Lochalsh	16/03/2020	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping up
454	Clachan Burn	Bettyhill	19/08/2020	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
		A870 at the junction with Auchingale Place		The Invert levels of the ditch have risen due to vegetation and silt deposition. Return ditch to orig
529	Knightswood Burn	Watten.	19/08/2020	roads.
532	Lochalsh Burn 4	Church Street, Kyle of Lochalsh	16/03/2020	Replace section of collapsed stone culvert with 400mm diameter pipe.
		Outlet of the Parks Farm Burn in to the Druid		
540	Parks Farm Burn	Temple Burn at the Grebe Avenue Hall	04/03/2020	Secure the chain to the screen which has been removed.
549	Scretan Burn Trib 3	Behind 1 Brinkman Terrace	04/03/2020	The culvert is blocked and requires clearing this is not an urgent job as there is an overflow char
				Remove a 10m X 2m area of silt deposition at the outlet of the box culvert which has restricted t
559	Mill Burn	Harris Road Inverness	04/03/2020	vegetation from the culvert inlet upto the footbridge which is opposite Milton Crescent
562	Druid Temple Burn	Old Edinburgh Road	04/03/2020	Remove all vegetation in and along both sides of the burn, all vegetation should be removed after
		Opposite the Vetinary Centre on the B9006		The outlet area of the culvert is suffering silt and vegetation deposition, ditch burn 10 metres down
572	Beechwood Burn	Culloden Road	04/03/2020	original invert levels.
				Culvert is surcharged the outlet is approx 75% surcharged due to deposation, ditch and return the
579	Culduthel Channel	Car Park next to Culduthel Mains Court,	04/03/2020	required to ensure the there are no blockages/silt deposits with the culvert.
	South Kessock			
580	Seawall	3 Areas in the seawall	16/07/2020	Repair missing stones sets in the seawall
596	Lochardil Burn	Lodge Park	04/03/2020	Remove all vegetation which is blocking the watercourse in the Lodge Park area.
599	Tower Burn	Caulfield Road North	02/03/2020	Remove all of the debris caught on the screen and the debris and silt accumulated just upsteam
600	Culloden Burn West	Behind the Culloden Centre	03/03/2020	Small area of silt and stones just upstream of the screen requires removal.
601	Mill Burn	Downstream of Diriebught House	04/03/2020	Clear all vegetation growing into and over the burn, from Diriebught House downstream up to a
602	Mill Burn	Premier Inn Car Park	03/03/2020	Remove all silt, stones and vegetation from the short open section
	•	•		

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out

aged screen.

upstream. Land ownership uncertain.

original invert level to help mitigate flooding on to the

nannel

d the width of the burn, remove areas of minor

after cutting downstream from the outlet and return burn to

the outlet to the original level, Jetting may also be

am.

a point opposite the small dwarf wall