

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
580	South Kessock Seawall	3 Areas in the seawall	03/03/2023	Repair missing stones sets in the seawall
608	Dingwall Flood Defences	Canal footpath At victoria park	03/03/2023	Infill and seal holes in the embankment where rabbits have been burrowing.
611	Dingwall Flood Defences	Canal footpath At victoria park	03/03/2023	Cut back and strim all vegetation growing in and along the flood embankment
624	Whaligoe Burn 1	Junction A99 road to Loch Watenan	20/02/2023	Remove blockage from within the road culvert. BEAR contacted and made aware of works required.
626	Mill Burn	Culvert under Sir Walter Scott Drive	03/03/2023	Remove all silt and stone deposition from the inlet and ditch 10m upstream from the inlet
628	Druid Temple Burn	Druid Temple Crescent, Inverness	03/03/2023	Remove all silt and stone deposition from the inlet and ditch 10m upstream from the inlet
633	Druid Temple Burn	Next to the playing ground at Grebe Avenue Hall	03/03/2023	Remove all vegetation lying in and across the burn which is restricting forward flow of water
635	Ault na Skiah	Adjacent to the Distributor Road (B8082) behind properties on Castle Heather Avenue	03/03/2023	remove silt accumulations from the culvert inlet which has reduced the culvert width by approx 50%, please remove any self seeded trees that are growing in the burn or on the burn sides.
636	SWFRC	SWRFC numerous locations	03/03/2023	Remove all vegetation gorse/whin are growing on the crown and sides of the flood relief channel. Currently growing is numerous areas
641	Eil Burn	Behind Burnside Lane	03/03/2023	Remove vegetation along ditch. Priority increased following updated observation of increased weed growth.
651	Dingwall Flood Defences	Sections 3, 4 and 5	03/03/2023	Complete clearance of all vegetation growing in sections 3, 4 and 5 of the flood defences
658	Slackbuie Channel	Junction of Culduthel Road and Green Drive	03/03/2023	Silt accumulations and a build up of debris/rubbish at the culvert, some of which is lying at the twin culvert inlets, please remove as much silt as possible and ensure inlets are clear.

\* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out