Works Number	Watercourse Name	Location	Date for Re- Inspection*	Description of Works
Turnbor	South Kessock			
580	Seawall	3 Areas in the seawall	19/02/2025	Repair missing stones sets in the seawall
	Dingwall Flood			
608	Defences	Canal footpath At victoria park	10/04/2024	Infill and seal holes in the embankment where rabbits have been burrowing.
	Dingwall Flood			
611	Defences	Canal footpath At victoria park	10/04/2024	Cut back and strim all vegetation growing in and along the flood embankment
626	Mill Burn	Culvert under Sir Walter Scott Drive	10/09/2024	Remove all silt and stone deposation from the inlet and ditch 10m upstream from the inlet
628	Druid Temple Burn	Druid Temple Crescent, Inverness	10/09/2024	Remove all silt and stone deposation from the inlet and ditch 10m upstream from the inlet
		Next to the playing ground at Grebe Avenue		
633	Druid Temple Burn	Hall	10/09/2024	Remove all vegetation lying in and across the burn which is restricting forward flow of water
		Adjacent to the Distributor Road (B8082) behind		remove silt accumulations from the culvert inlet which has reduced the culvert width by approx
635	Ault na Skiah	properties on Castle Heather Avenue	17/06/2024	growing in the burn or on the burn sides.
636	SWFRC	SWRFC numerous locations	10/09/2024	Remove all vegetation gorse/whin are growing on the crown and sides of the flood relief channel
641	Eil Burn	Behind Burnside Lane	04/05/2024	Remove vegetation along ditch. Priority increased following updated observation of increased w
	Dingwall Flood			
651	Defences	Sections 3, 4 and 5	23/07/2024	Complete clearance of all vegetation growing in sections 3, 4 and 5 of the flood defences
				Silt accumulations and a build up of debris/rubbish at the culvert, some of which is lying at the tw
658	Slackbuie Channel	Junction of Culduthel Road and Green Drive	17/06/2024	possible and ensure inlets are clear.
				The outlet of structure 60 is suffering silt and vegetation deposition approx 90% surchaged, the
		Opposite the Veterinary Centre on the B9006		surcharging, deposition is deflecting waterflows towards the sidewall, ditch burn 10 metres down
663	Beechwood Burn	Culloden Road	10/09/2024	the inlet to return burn to original invert levels.
				The culvert outlet is 50% surcharged due to windblown trees and woody debris lying across the
664	Ault na Skiah	Culvert outlet opposite Evan Barron Rd	10/09/2024	down to the boundary fence of the property. Clear all woody debris from the open section.
		Near Passing Place Lay-by next to Brahan		Heavy Vegetation surrounding Inlet & all along Bank Upstream to Structure 60 & Downstream to
690	Ben View Burn	View, Upper Arcan Road Marybank.	05/05/2024	from Inlet of S70 & all along Downstream between S70 & S72.
		Knockbain Silt Traps, Blackwells Court.		Silt build up across all 3 Screens, particularly in far left & right Screens. Very Large Stone wash
694	Knockbain Burn	Dingwall	05/05/2024	3 Screens to be ditched out & removed.
702	Tain Burn 2	Within St Vincent Estate	27/04/2024	Section 18 Letter issued to the Homeowners. Heavy Vegetation & Woody Debris within a sectio
703	Miller Road Burn	Miller Road, Cromarty	13/05/2024	Silt build up along Watercourse D/S from Outlet and within Culvert itself. Silt to be removed/ dite
704	Dores Burn 1	Torr Gardens, Dores	14/05/2024	Vegetation dumped on top of Watercourse, blocking the Culvert Inlet. Needs to be removed.
708	Hill Terrace Burn	Hill Terrace, Kinlochleven	23/05/2024	Wire Fence along Bank collapsed should be repaired to prevent blockages & prevent public fall
710	Hill Terrace Burn	Hill Terrace, Kinlochleven	23/05/2024	Silt/ Stone build up near Inlet. Should be removed to ensure unrestricted flow.
714	Slackbuie Spring	Upper Slackbuie along SWFRC, Inverness.	17/06/2024	Vegetation on spill to be cut down to geo fabric underneath.
			11/00/2021	Screen has been tilted & raised by small log/ stump. Stone silt washed up LHS near Screen & c
717	Lochardil Burn	Along Sir Walter Scott Drive (A8082), Inverness	17/06/2024	Screen to be returned to original position.
719	Mill Burn	Sluice Gate near Millburn Court, Inverness	17/06/2024	RHS of Sluice blocked with Debris, forcing all Waterflow into LHS should be cleared.
				Screen blocked & surcharged, Water overtopping Screen into WC but not on to Banks. Most of
721	Scretan Burn	Caulfield Road North, Inverness	17/06/2024	Remove silt.
724	Knockbain Burn	Knockbain Burn, near Gorstan, Dingwall	03/05/2024	Build up of Silt on LHS near Screen - Should be cleared
				Debris & Large Branches blocking RHS of Culvert Inlets, there is also a build up of Silt/ Stones
726	Kylintra Burn	Woodburn Crescent, Grantown-on-Spey	12/04/2024	should be removed & Silt ditched out of Culvert.
. 20		Debris Screen near SSE Garage, A82 Fort	12/01/2021	Screen Blocked & Surcharged 50% from Large Debris & Leaves. Rest of Screen to be cleared
728	Balantoul Burn	Augustus.	27/04/2024	removed also.
730	Ardival Burn	Rear entrance to Wyvis Hotel, Strathpeffer	03/05/2024	Old Stone Culvert has collasped, causing Inlet to Pool/ Surcharge & overtop over Road. Culvert
		Olrig Cemetery, road leading to St Trothan's		Dual Stone Culvert/ Cundy has collapsed in middle of Culverted section parallel to Road. Multip
732	Olrig Cemetery Burn	Church, Castletown	23/04/2024	Inlet U/S. Repair/ replace collapsed section, collect side-cast Debris near Screen.
	South West Inverness	Large Screen at end of SWFRC, Essich Road,		
733	Flood Relief Channel	Inverness	17/06/2024	Lower Screen 50% blocked with Vegetation. Screen should be cleared entirely to ensure un-res
733	Scretan Burn	Caulfield Road North, Inverness	17/06/2024	Inlet blocked with Wooden Debris. Debris should be removed to ensure un-restricted flow.
1 34			17/00/2024	Washed down Debris accummulating on Screen, buried underneath mound of Silt/ Stones etc.
736	Tower Burn	Rowan Grove, Inverness	08/05/2024	to wash downstream.
100		Culloden Woods, Footpath that runs behind	00/03/2024	
737	Culloden Burn West	Loch Lann Ct & Redburn Ave	17/06/2024	Screen blocked with washed down Debris, Silt, Stones etc. Should be cleared to ensure un-rest
101		Lipspection denotes when the re-inspection is due		

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out

x 50%, please remove any self seeded trees that are

nel. Currently growing is numerous areas

twin culvert inlets, please remove as much silt as

ne inlet of structure 70 has similar issues although not ownstream from the outlet and 10m upstream from

he watercourse for the majority of the open section

n to S72. Vegetation to be cut back 10m Upstream

shed down into Screen on LHS facing D/S. All Silt in

tion of the Watercourse within property boundaries. ditched to ensure unrestricted flow.

alling in.

a centre slightly U/S. Silt to be ditched & removed &

of the blockage is Silt build up, which has built up.

es within the Outlet of the middle Culvert. Debris

d with large Debris removed. Side-cast Debris to

ert to be replaced with new Pipe & Headwall. tiple piles of side-cast Debris surrounding Screened

estricted flow

c. Debris should be cleared to allow the Silt/ Stones

estricted flow.