The Highland Council: Scheduled Watercourse Maintenance Works - Complete February/March 2024

Works Number	Watercourse Name	Location	Date Works Carried Out	Description of Works
				Flap Valve unable to be Inspected as valve can't be opened due to Stones & Seaweed build up. If water is unable to flow unrestricted then the
678	Rhives Burn	Golspie Beach	19/03/2024	result of Flooding further upstream is likely.
		Along boundary fence of Tulloch Farm,		Section of Wire Fencing U/S from S100 blocked with Leaves. S18 Letter issued to Landowner to clear Leaves from Fence & cut bottom Wire Link
716	River Peffery Trib1	Dingwall. U/S from S100		on bottom of Fence to allow Leaves to flow down overspill section unrestricted.
				Screen fully Blocked/ Surcharged during SW Incident. Area surrounding Structure pooling & washed with large amounts of Silt. This blockage
				resulted in Castle Heather Park & Balloan Road to become flooded, with Balloan Rd being closed by Roads. Inspector cleared 75% of Screen on
		Debris Screen on Sir Walter Scott Drive		07/02/24, Waterlevels had reduced afterwards but Silt still previlant. All Silt should be removed, this should reduce Waterlevel further. Once levels
729	Ault na Skiah	(A8082), Inverness	06/03/2024	have dropped, rest of Screen should be cleared.
		Woodland section behind Sgriodan, North		Screen has blinded following Severe Weather on the 5th Feb. Ditch Burn back down to original invert level and ditch 10 metres upstream from
731	Bellfield Burn	Kessock	07/03/2024	Inlet.