THE HIGHLAND COUNCIL

AUDIT AND SCRUTINY COMMITTEE 24 SEPTEMBER 2014

| Agenda | 8 |
|--------|----------|
| Item | |
| Report | AS/20/14 |
| No | |

INSPECTION OF EQUIPMENT IN SCHOOLS – INTERNAL AUDIT REPORT UPDATE

Report by Director of Development & Infrastructure

Summary

This report informs Members on the objectives and findings of the Audit Report presented to the Audit and Scrutiny Committee on 19th June 2014, and updates them on progress against the agreed action plan.

1. Background

- 1.1 The Audit and Scrutiny Committee considered an Internal Audit Report on the Inspection of Equipment in schools at their meeting on 19 June 2014. In accordance with the Local Code on Corporate Governance that report has also been reported to the Planning, Development and Infrastructure Committee on 20 August 2014, and the Education, Children and Adult Services Committee on 28 August 2014.
- 1.2 This report sets out the main objectives and findings of the report (**Appendix 1a**) and provides an update in relation to the agreed management actions (**Appendix 1b**).

2. Inspection of School Equipment

- 2.1 The audit examined the contractual management arrangements in respect of the Inspection and Testing of Plant, Equipment and Fixed Electrical Installations contract that was in place at that time. That contract was administered by the Property Management Section within the then Housing and Property Service on behalf of Council Services, and each Service had a nominated officer to act on their behalf.
- 2.2 As a result of concerns regarding the overall performance of the contractor, gym equipment and fixed electrical installation inspections and testing were removed from the contract during the course of the audit review.
- 2.3 The audit findings relate to the arrangements that were in place prior to retendering taking place in January 2013, therefore many of the issues raised have been resolved through the introduction of the new contracts, which are now managed by dedicated staff.

3. Review Objectives

- 3.1 The objectives of the review were as follows:
 - there are appropriate contract arrangements in place for the inspection and testing of equipment and this is managed properly;

- the Development & Infrastructure Service maintain up-to-date, accurate and complete records of all inspections and subsequent reports. Particular emphasis will be placed upon the process for the inspection of equipment in schools;
- the appropriate action is undertaken and the relevant officers are informed following receipt of the inspection reports; and
- there are appropriate monitoring arrangements in place to ensure that all remedial actions are addressed within the relevant timescale. Emerging themes or issues are promptly identified and escalated in order that any costs can be identified and notified to Care and Learning management.

4 Audit Findings

- 4.1 The audit found that these contracts had historically not been appropriately resourced, administered and scrutinised, with appropriate steps taken to resolve issues.
- 4.2 The audit report contains 13 recommendations, 2 of which are categorised as high priority. The recommendations have been accepted by management and the table below highlights the level of progress achieved with the implementation of all the agreed actions:

4.2.1

| | Summary List of Agreed Actions and Status as of 12/09/2014 | | | | | | |
|------|--|--------|--|-------------------------------------|--|--|--|
| Item | Report Ref | Grade | Management Agreed Action Progress | Responsible Officer | Target Date | | |
| 1 | 3.1.1 Medium | | 1no Sub-action extended to 31/1014 | Property Risk Management Officer | Extended to 31/10/14 to allow new policies to be agreed with restructured Council Services | | |
| | | | 2no Sub-actions are Complete | Property Manager | Complete | | |
| 2 | 3.1.2 | Medium | 3no Sub-actions are Complete | Property Manager | Complete | | |
| 3 | 3.1.3 | Low | 1no Action is Complete | Property Manager | Complete | | |
| 4 | 3.1.4 | High | 3no Sub-actions are Complete | Head of Property | Complete | | |
| 5 | 3.1.5 | Medium | 3no Sub-actions are Complete | Property Manager | Complete | | |
| | | | | | | | |
| 6 | 3.2.1 | Medium | 1no Action is Complete | Property Manager | Complete | | |
| | | | 1no Sub-action Original Target date is 31/03/2015 | Property Manager | 31/03/2015 In Progress | | |
| 7 | 3.2.2 | Medium | 1no Sub-action extended to 31/10/14 | Property Risk Management Officer | Extended to 31/10/14 to allow new policies to be agreed with restructured Council Services | | |
| 8 | 3.2.3 | Medium | 2no Sub-actions are Complete | Property Manager | Complete | | |
| 9 | 3.2.4 | High | 1no Sub-action extended to 28/11/14 | Property Manager | Extended to 28/11/14 to allow electrical contractor to complete North programme of inspections | | |
| | | | 1no Sub-action Original Target date is 29/07/2016 | Property Manager | 29/07/2016 In Progress | | |
| 10 | 3.2.5 | Medium | 1no Action is Complete | Property Manager | Complete | | |
| | | | | | | | |
| 11 | 3.3.1 | Medium | 1no Action is Complete | Property Manager | Complete | | |
| 12 | 3.3.2 | Medium | 1no Sub-action extended to 28/11/14 | Property Manager | Extended to 28/11/14 to ensure Client Services agree new procurement/remedial works procedures. | | |
| | | | 2no Sub-actions are Complete | Property Manager | Complete | | |

| 13 | 3.4.1 | Medium | 1no Action extended to 28/11/14 | Head of Support Services and Head of Property | Extended to 28/11/14 to ensure that process for remedial works is fully deployed. |
|----|-------|--------|---------------------------------|---|---|
|----|-------|--------|---------------------------------|---|---|

4.3 In addition to the specific actions identified in the audit report, the Care & Learning Service has reallocated existing budgets to ensure that there is sufficient funding to meet the annual cost of all inspection contracts and related remedial works. This will ensure that these contracts are adequately resourced from now onward.

5. Implications

5.1 This Audit report demonstrates the need to ensure that the Council's assets are managed both efficiently and effectively, and that service contracts are sufficiently resourced to ensure continued compliance with existing and new statutory legislation.

Recommendation

Members are invited to note the findings of the Audit Report presented to the Audit and Scrutiny Committee on 19 June 2014 and the progress being made against the agreed action plan.

Designation: Director of Development and Infrastructure

Date: 12 September 2014

Author: Finlay MacDonald, Property Manager

Appendices: Audit Report Summary & Action Plan

AUDIT REPORT SUMMARY

Report Title

Care & Learning Service / Development & Infrastructure Service - Inspection of Equipment in Schools

| Danast Na | Time of Airdit | Janua Data |
|------------|----------------|------------|
| Report No. | Type of Audit | Issue Date |

| HC13/017.bf.bf | System | Draft Report | 14/05/14 |
|----------------|--------|--------------|----------|
| | | Final Report | 10/06/14 |

1. Introduction

- 1.1 This audit was undertaken as part of the annual plan for 2012/13 to examine the contractual management arrangements in respect of the Inspection and Testing of Plant, Equipment and Fixed Electrical Installations contract (PAS-INS125) (hereafter to be referred to as "the contract"). The contract commenced on 01/04/07 and was due to expire on 31/03/10. It was then extended for a further 3 years until 31/03/13.
- 1.2 The Property Management Section, Development & Infrastructure Service are the contract administrators on behalf of the interested Council Services such as Care and Learning Service. Each Service has a nominated officer to act on the Service's behalf.
- 1.3 As a result of concerns regarding the overall performance of the contractor, gym equipment, and fixed electrical installation inspections and testing were removed from the contract from 10/12/12 and 01/01/13 respectively. This took place during the course of the audit review.
- 1.4 A number of new contract arrangements were then put in place:
 - In January 2013, a new contract for the inspection and testing of the fixed electrical installations was awarded from February to June 2013, covering all out of date inspections up to the end of May 2013. Another contract was then let to cover the fixed electrical inspections from June to December 2013. Furthermore, new contracts for the inspection and testing of going out of date fixed electrical installations were introduced in February and March 2014 to cover properties within South and North areas respectively. In addition, a new contract was awarded in May 2014 to provide a 2 year cover for routine inspections.
 - The remaining testing and inspection elements, including gym equipment, were included with a contract for the period April 2013 to March 2014. An interim contract is currently in place which expires during August 2014. A replacement contract is presently out to tender.
- 1.5 The audit findings below relate to the arrangements that were in place prior to re-tendering taking place in January 2013.

2. Review Objectives

The objectives of the review were to ensure that:

- 2.1 There are appropriate contract arrangements in place for the inspection and testing of equipment and this is managed properly.
- 2.2 The Development & Infrastructure Service maintain up-to-date, accurate and complete records of all inspections and subsequent reports. Particular emphasis will be placed upon the process for the inspection of equipment in Schools.
- 2.3 The appropriate action is undertaken and the relevant officers are informed following receipt of the inspection reports
- 2.4 There are appropriate monitoring arrangements in place to ensure that all remedial actions are addressed within the relevant timescale. Emerging themes or issues are promptly identified and escalated in order that any costs can be identified and notified to Care and Learning Management

3. Main Findings

The main findings of the review, referenced to the above review objectives, are as follows:

- 3.1 This objective was not achieved as:
 - A number of the expected documents were either not in existence or have not been recently updated:
 - o The policies which would support inspection and testing requirements including:
 - The "Electrical at Work" policy which has not been subject to recent review;
 - There are no policies for Lifting, Pressure Systems, Local Exhaust Ventilation (LEV) and Gym Equipment.
 - It was highlighted during this audit that there was no service contract in place for LEV equipment and the arrangements in place were only partially compliant with Control of Substances Hazardous to Health (COSHH) requirements. However, the COSHH requirements have since been addressed.
 - There was no procedural guidance issued to assist officers with their required roles and responsibilities.
 - In addition, no documents were held to support the contract extension for the period April 2011 March 2012.

There was limited contract monitoring during the period January 2010 to December 2011. This was undertaken by way of contract progression meetings which discussed contract and performance issues. However, only 2 meetings were held during these two years. In addition, the meetings held in 2012 were not minuted.

The contractor failed to provide the appropriate detail of report and instead provided a summarised form of testing results. In addition, review of a sample of fixed electrical inspection reports highlighted that the overall opinion did not always correlate with the individual defects identified, making it difficult to assess their importance and necessity for action.

It was not possible to establish whether the contract sums paid were accurate due to the absence of any formal contract variations after March 2009. In addition, the contractor failed to provide evidence that the schedule of works was completed, and there is no documentation to show how the annual price increases were calculated and applied.

The contractor was paid by an Officer within the Finance Service upon receipt of a monthly invoice, with no recourse to the Property Management Section. Services have then been recharged on the same basis as the allocation of insurance premiums rather than works undertaken. In addition, High Life Highland buildings were omitted in calculating the charges to the Care and Learning Service for 2012/13.

3.2 This objective was not achieved as the contractor failed to use the Council's unique site reference numbers; using their own instead. Despite requests for the contactor to reconcile their information to that held by the Council, this was not done.

There is no Council wide asset register of equipment to be inspected and therefore, it could not be established if all assets and equipment held was actually inspected.

There were issues with the contractor's database not presenting all relevant information and this was addressed through the provision of additional reports. Since the previous contract was terminated and a new contractor commenced, this has highlighted further concerns about the quality of the inspections previously undertaken. In particular, where a site has multiple buildings, only one received the fixed electrical inspections (FEI) and the Inspection and Testing (I&T) programme is expanding due to an increased number of items being found by the new contractor.

Access to the contractor's database, where the inspection reports were held, ceased from 31/03/13 due to termination of the contract. In order to address this, all reports were downloaded manually but there are issues with the completeness and accuracy of this data. In addition, the Care and Learning Service's records require updating to ensure that full records of inspections are held.

One school had received an FEI during the course of the contract but this was not recorded on the database and the inspection date is unknown. It could not be confirmed whether the FEIs are in accordance with the expected 5 yearly timescale due to no schedule of works being provided by the contractor. In addition, equipment had been inspected more

regularly than standards direct at one High School examined.

- 3.3 This objective was partially achieved as the Plant & Gym Equipment, records show that Care and Learning Officers are requesting and then reviewing the reports within 1-3 months of inspection. However, this is only since March 2012 and there were significantly delays before this date. The FEI reports were not being addressed in a timely manner with delays averaging 19 months.
 - In addition, the remedial works were not instructed by Care and Learning Officers who stated that this was due to an absence of appropriate contractors on the Framework Agreement. In addition, where works were instructed there was no evidence to demonstrate that this was subsequently completed.
- 3.4 As a result of the findings at (iii) above, this objective was not achieved.

4. Conclusion

- This contract has historically not been appropriately administered and scrutinised, with appropriate steps taken to resolve issues. Council sites have potentially been put at risk of delayed inspection. The contractor did not align systems to match Council listings as requested and supply requested documentation in relation to the contract. There has been a lack of joint input over payments, with no reconciliation to works completed. It is unclear whether remedial works highlighted by the inspection and testing reports were being authorised and competed appropriately.
- 4.2 The Contract Administrator had attempted to address these concerns by subdividing the contract, putting new inspection and testing contractors in place and resuming control of contractor payments. A download of the database provided by the contractor, was undertaken, prior to the termination of access. It was advised that these reports will be entered onto the new property database, K2.
- In moving forward, there should be improvements in the level of contract documentation held to provide sufficient guidance to officers, support contract changes, reconcile work undertaken and demonstrate adherence to the contract requirements. Council polices which cover inspection and testing arrangements should be subject to regular review. The contract should be regularly monitored and necessary action taken if the contractor deviates from the contract specification. Work should be undertaken to produce an accurate position of site inspection frequencies to ensure compliance to regulation and fully uncover the impact of any under-inspection by the previous contractor.
- As a result, there are 2 high, 10 medium and 1 low grade recommendations in this report. 3 medium and the low grade action have been completed, with the majority of the remaining actions due to be completed by the end of September 2014. There is one longer term action which relates to ensuring that all council buildings have a valid Fixed Electrical Inspection and Test report available by the end of July 2016.

5. Audit Opinion

The opinion is based upon, and limited to, the work performed in respect of the subject under review. Internal Audit cannot provide total assurance that control weaknesses or irregularities do not exist. It is the opinion that **Limited Assurance** can be given in that weaknesses in the system of controls are such as to put the system objectives at risk, and/ or the level of non-compliance puts the system objectives at risk.

Appendix 1b

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service - Inspection of Equipment in Schools

HC13/017.bf.bf

The Action Plan contains 13 recommendations as follows:

| Description | Priority | Number |
|---|----------|--------|
| Major issues that managers need to address as a matter of urgency. | High | 2 |
| Important issues that managers should address and will benefit the Organisation if implemented. | Medium | 10 |
| Minor issues that are not critical but managers should address. | Low | 1 |
| Total recommendations | | 13 |

| | | | | | IMPLEMENT | ATION |
|--------|--------|---|--------------------------------|-----------------------------|---------------|------------------------|
| REPORT | | | | MANAGEMENT AGREED | RESPONSIBLE | TARGET |
| REF. | GRADE | FINDING | RECOMMENDATION | ACTION | OFFICER | DATE |
| 3.1.1 | Medium | Various documentation which would | The Property Management | (1) All existing and future | Property Risk | <mark>29/08/14</mark> |
| | | have been expected as part of good | Section should ensure that: | Inspection and Testing | Management | Extended |
| | | contract arrangements could not | (1) Appropriate polices are in | policies will be updated | Officer | <mark>to</mark> |
| | | found, in particular: | place, up to date and | and subsequently | | <mark>31/10/14.</mark> |
| | | (1) A number of expected Council | reviewed regularly. | reviewed annually or in | | |
| | | policies which support Inspection | | response to legislative | | |
| | | & Testing arrangements either did | | or other requirements. | | |
| | | not exist or had not been updated | | | | |
| | | for several years. In particular: | | | | |
| | | The "Electrical at Work" policy | | | | |
| | | was subject to review; | | | | |
| | | There are no policies for | | | | |
| | | Lifting, Pressure Systems, | | | | |
| | | Local Exhaust Ventilation and | | | | |
| | | Gym Equipment. | | | | |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service – Inspection of Equipment in Schools HC13/017.bf.bf

| | | | | | IMPLEMENT | ATION |
|-------------------|-------|--|---|--|---------------------|----------------|
| REPORT G | GRADE | FINDING | RECOMMENDATION | MANAGEMENT AGREED ACTION | RESPONSIBLE OFFICER | TARGET DATE |
| 3.1.1 (cont'd) | | (2) There is no guidance available to officers detailing their roles and responsibilities. | (2) I&T guidance is in place to ensure all involved individuals are aware of their role and responsibilities. | (2) Inspection and Testing procedures for contract management arrangements will be further developed to ensure individuals are aware of their role and responsibilities. New, robust management arrangements will ensure that this recommendation is achieved. | , , | Complete |
| | | (3) There is no formal documentation | (3) All appropriate contract | (3) Appropriate contract | , , | Complete |
| | | held to support the contract | documentation is held, | documentation is now | Manager | |
| | | · | 5 5 5 | _ | | |
| | | | | responsibilities. New, robust management arrangements will ensure that this recommendation is achieved. (3) Appropriate contract | Property Manager | С |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service – Inspection of Equipment in Schools HC13/017.bf.bf

| | | | | | IMPLEMENT | ATION |
|--------|--------|---|---|---|---------------------|----------|
| REPORT | | | | MANAGEMENT AGREED | RESPONSIBLE | TARGET |
| REF. | GRADE | FINDING | RECOMMENDATION | ACTION | OFFICER | DATE |
| 3.1.2 | Medium | There was limited contract monitoring during the period January 2010 to December 2011. In addition, few contract progress meetings were held and minutes of these were not always retained. This is particualary important as issues were identified with the contractor failing to conform with the contract requirements. | the contract is addressed with the contractor in a prompt manner. Where Contract progress meetings are held, the Service should ensure that appropriate records and minutes are held for future | measures for contract out-puts are now in place. Contract management meetings are now in place for service contracts. Non-conformance issues when identified will be dealt with in timeous manner. Contract progress Meeting Minutes are being taken and recorded in relevant | Property Manager | Complete |
| 3.1.3 | Low | In addition, the contractor failed to provide the required report format, choosing instead to provide a less detailed summary report. | reference. The Property Management Section should ensure that future contracts explicitly highlight what is required from the contractor in terms of reporting requirements, including compliance with statutory legislation and quality control requirements. | project files. All future contracts will be explicit on what outputs are required from the appointed contractor and this will be enforced by the responsible Contract Administrator. | Property Manager | Complete |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service – Inspection of Equipment in Schools

| | | | | | IMPLEMENTA | ATION |
|--------|-------|--|---|---|---------------------|----------|
| REPORT | | | | MANAGEMENT AGREED | RESPONSIBLE | TARGET |
| REF. | GRADE | FINDING | RECOMMENDATION | ACTION | OFFICER | DATE |
| 3.1.4 | High | It is not possible to establish if the contract sums paid were correct as: No records were held to evidence changes to contract sum after 2008/09. No Contract Variations found for 2009/10 onwards. No schedule of works was provided by the contractor and it is not known if the expected works were undertaken. No records were held to evidence the basis of annual price increases applied to the contract. | Service should ensure that contractual arrangements are adhered, in that: • All contract variations should be recorded, reconciled to contract annual sums and once submitted to contractor, the contract variation checked to ensure the appropriate action has | been allocated and will be supplemented when necessary to ensure that Contract Administrators are able to: Record all variations Reconcile contract payments Apply annual contract | Head of Property | Complete |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service - Inspection of Equipment in Schools

| | | | | | IMPLEMENT | ATION |
|----------------|--------|--|--|--|---------------------------|----------------|
| REPORT REF. | GRADE | FINDING | RECOMMENDATION | MANAGEMENT AGREED ACTION | RESPONSIBLE OFFICER | TARGET DATE |
| 3.1.5 | Medium | The arrangements for the payment of invoices to the contractor were unsatisfactory as these were processed by the Insurance & Risk Section with no input from Property Management Section to confirm amount or completed works invoiced. It should be noted that this has ceased with termination of the contract. In addition, the process for the recharge of the contract sum is unsatisfactory as it was based on insurance premiums rather than the inspection works. | Service should ensure that there are appropriate arrangements in place for the payment and recharge of contract sums, in that: • Where they administer contracts then they have the corresponding responsibility for the authorisation and payment of any sums due to the contractor. | Contract payment mechanisms have been reviewed and payments are being reconciled. | Manager Property Manager | Complete |
| 3.2.1 | Medium | The contractor failed to use the Council's unique site identifiers and instead used their own numbering system, and the two sets of information were never fully reconciled. As a result there is no assurance that all expected items have been inspected in accordance with the contract requirements. | The Property Management Section should ensure that future contracts include the explicit condition that contractors include the Unique Council Site identifiers, as provided within the contract in any correspondence and/ or reporting. | All recent and future contracts have or will include the Council's own unique property code for each property. | Property Manager | Complete |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service - Inspection of Equipment in Schools

| | | | | | IMPLEMENT | ATION |
|----------------|--------|---|----------------|--|--|--|
| REPORT REF. | GRADE | FINDING | RECOMMENDATION | MANAGEMENT AGREED ACTION | RESPONSIBLE OFFICER | TARGET DATE |
| 3.2.2 | Medium | The absence of an asset register means that it cannot be established if all assets and equipment were inspected in accordance with the contract requirements. | | (1) Consultation with Council service RPOs will take place to ensure that asset registers are verified. (2) Property Policy will require Client Service Managers to ensure that | Property Manager Property Risk Management | 31/03/15 In Progress 29/08/14 Extended to 31/10/14 |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service – Inspection of Equipment in Schools

| | | | | | IMPLEMENT | ATION |
|----------------|--------|---|---|---|---------------------|----------------|
| REPORT REF. | GRADE | FINDING | RECOMMENDATION | MANAGEMENT AGREED ACTION | RESPONSIBLE OFFICER | TARGET DATE |
| 3.2.3 | Medium | Following the appointment of the new contactor this has highlighted further issues with previous contactor's performance, namely: • Where a site contains multiple buildings, only one building was fully inspected; • An increased number of items requiring inspection have been identified. It is expected that it will take a full 5 | The Property Management Section should undertake a review to discover the full impact of: • The under-inspection of fixed electrical inspection. There is a risk that sites are not compliant with Inspection and testing regulations and risks are posed to individuals operating within the sites. | A review of inspection records has been undertaken and interim Inspection and Testing contracts have been put in place to resolve any risks that may exist due to any omissions of the previous Inspection and Testing contractor. | Property Manager | Complete |
| | | year inspection cycle to obtain accurate data. | | Contract payments to the previous poorperforming contractor were reduced to mitigate the need to engage new contractors to carry out an enhanced programme of inspection and testing. Council Services are being notified where site risks are identified and any failed equipment/installations are now taken out of operation until they can be repaired or replaced. | Property Manager | Complete |

Report Title

Report No.

Care & Learning Service / Development & Infrastructure Service - Inspection of Equipment in Schools

| | | | | | IMPLEMENTATION | |
|--------|-------------------|--|---|--|-------------------------------------|--|
| REPORT | | | | MANAGEMENT AGREED | RESPONSIBLE | TARGET |
| | | | | | OFFICER | DATE |
| 3.2.4 | GRADE High | The contractor provided all inspection reports on their database (Crimson). In response to access being removed as a result of termination of the contract, the latest site reports were downloaded from Crimson and manually re-named. The report date has been used to schedule when the next inspection should be undertaken. However, the reports provided are not just inspections, and so there is the risk that the wrong inspection date is used and the required inspection periods are not complied with. It was also identified that Care and Learning Service's records were not up to date, and in agreement with Crimson. Also prompt action was not always taken to address any remedial works identified. | RECOMMENDATION The Property Management Section should ensure that: (1) The downloaded Crimson data is cleansed to provide an accurate picture of when sites were last inspected. Any sites not listed on Crimson and those with inspection periods exceeding standard guidelines should be prioritised for inspection. (2) Services are notified that a back-up of Crimson inspection & testing reports is held. | ACTION The Crimson data cannot be relied upon for the purpose described. More effective actions are: Two interim Fixed Electrical Inspection and | OFFICER Property Manager Property | 26/09/14 Extended to 28/11/14 29/07/16 In Progress |
| | | | | report available by the end of July 2016. | | |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service - Inspection of Equipment in Schools

| | | | | | IMPLEMENT | ATION |
|--------|--------|---|--|--|---------------------|----------|
| REPORT | | | | MANAGEMENT AGREED | RESPONSIBLE | TARGET |
| REF. | GRADE | FINDING | RECOMMENDATION | ACTION | OFFICER | DATE |
| 3.2.5 | Medium | It is not possible to establish if inspections were performed within the specified timescale as: • Previous inspection dates for FEI were not recorded on Crimson. • No record on Crimson of South Lodge Primary being FEI inspected. The Contract Administrator confirmed that had been undertaken but could not specify the date. • At one school plant equipment was being inspected more | The Property Management Section should ensure that the inspection periods are monitored to ensure that these are in accordance with the contract's schedule of works and required standards. Any variances should be promptly addressed with the contractor. | Regular contract progress meetings are being held with the appointed service contractors to ensure that contract programmes are adhered to and that contract specifications are being followed. Any deviation from contract specifications would be discussed and resolved during regular progress | Property Manager | Complete |
| | | regularly than required. | | meetings with the service | | |
| 3.3.1 | Medium | It was not possible to verify that inspection reports were being reviewed and forwarded in a timely manner as this is not always evidenced. In addition, there were significant delays, averaging over 19 months, in the forwarding of some reports. | The Property Management Service should remind Service contract representatives that the review and forwarding of all testing and inspection reports should be undertaken in a reasonable timeframe and the appropriate records updated to evidence this. | Service contract reports will be circulated timeously to Client Service Managers. Contract Administrators will monitor and record the circulation of inspection reports to Client Service Managers. The new Inspection and Testing contract has a web based portal which provides Council Premises Managers access to copies of all inspection certificates. In addition to this all inspection certification is now e-mailed out to Premises Managers for their review. | Property Manager | Complete |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service - Inspection of Equipment in Schools

| | | | | | IMPLEMENT | ATION |
|--------|--------|--|--|---|---------------------|--|
| REPORT | | | | MANAGEMENT AGREED | RESPONSIBLE | TARGET |
| REF. | GRADE | FINDING | RECOMMENDATION | ACTION | OFFICER | DATE |
| 3.3.2 | Medium | (1) It was not possible to confirm whether remedial works highlighted by I&T reports were authorised and completed. | (1) The Property Management Section should: Remind the relevant Services to ensure that appropriate information is held to evidence any remedial | (1) Instructions from Client Services to proceed with remedial works will be recorded in each service contract file. Guidance will be distributed to Client | Manager Property | Complete |
| | | | remedial works authorised. • Ensure appropriate guidance is distributed on how to operate the new contractor's inspection and testing management system. | distributed to Client Services to ensure that they are able to operate and interrogate the records held in the inspection and testing database. | Manager | |
| | | (2) It was established that a number of Care and Learning remedial works were not addressed. The reason provided for this was the lack of suitable contractors on the Framework Agreement. | (2) The procedure for requesting remedial works should be documented and distributed to relevant Services. This should include links to the Framework Agreement or Service contracts. | (2) A procedure for requesting procurement and completion of remedial works will be established and communicated to Client Service Managers. | , , | 29/08/14 Extended to 28/11/14 |
| | | | (3) Where Services identify the absence of specialist contractors on the Framework Agreement, they should notify Development & Infrastructure Service staff accordingly in order that an appropriate solution can be identified. | (3) Development and Infrastructure Service will procure specialist contracts on behalf of Client Service Managers via the Councils Quick Quote process or alternatively under the full tendering procedure. | Property Manager | Complete |

Report Title Report No.

Care & Learning Service / Development & Infrastructure Service – Inspection of Equipment in Schools HC13/017.bf.bf

| | | | | | IMPLEMENT | ATION |
|--------|--------|---------------------------------------|------------------------------------|-----------------------------|-----------------|-----------------------|
| REPORT | | | | MANAGEMENT AGREED | RESPONSIBLE | TARGET |
| REF. | GRADE | FINDING | RECOMMENDATION | ACTION | OFFICER | DATE |
| 3.4.1 | Medium | There is limited monitoring of | The Property Management | A process of monitoring and | Head of Support | 26/09/14 |
| | | remedial works undertaken by the | Section should remind the | reporting that contract | Services and | Extended |
| | | Contract Administrator. Therefore, it | relevant Services to ensure that | remedial works are being | | |
| | | was not possible to establish if all | appropriate information is held to | completed to the required | Property | <mark>28/11/14</mark> |
| | | • | evidence that remedial works are | standards and timescales | | |
| | | undertaken. Also as stated at 3.3.2 | | will be developed and | | |
| | | above, Care and Learning remedial | | implemented. | | |
| | | works have not been undertaken. | | | | |