

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
216	Rhives Burn	Ben Braggie car park	19/03/2016	Remove debris and repair the collapsed culvert in the Ben Braggie car park. Landowner contacted and asked to carry out works.
224	Blair of Tarradale Burn	A832 200m west of B9169 junction	15/04/2016	Debris and vegetation to be cleared from culvert inlet.
267	Macrae Grove Burn	To the rear of 12 Macrae Grove	06/03/2016	Ditch at culvert inlet is overgrown causing partial blockage of the screen. Area immediately upstream of screen to be cut back and dead vegetation removed. Landowner contacted and asked to carry out works.
284	Mill Burn	Opposite 35 Harris Road	22/03/2016	Scottish Water sewer outfall headwall is partially collapsed into the watercourse. Headwall to be repaired. Scottish Water informed of works required.
296	Kinellan Burn	Adjacent to A834, upstream of St Anne's Episcopal Church	05/06/2016	New screen arrangement to be designed and installed at culvert inlet to replace existing damaged screen.
330	Ault na Skiah	Upper Slackbuie	03/11/2015	Woody debris to be removed from screen which is 80% blinded. Gravel deposits to be cleared from upstream side of screen also.
354	Lochalsh Burn 5	Kyle of Lochalsh	17/02/2016	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping upstream. Land ownership uncertain.
373	Tower Burn	Cranmore Drive	08/03/2016	Suspected debris from tree clearance work left in burn causing blockage risk. Remove from Burn. Passed to SSE.
395	Essich Burn	Torbreck/Ness Castle	19/03/2016	Stones and rubble blocking one inlet to a double culvert. Landowner contacted and requested to remove blockage.
403	Kylintra Burn	Culverts at the entrance to Woodburn Crescent	13/07/2016	Remove silt deposition which is restricting forward water flow from the culverts.
412	Ardival Burn	Culvert inlet near to the Ben Wyvis Hotel service entrance	17/04/2016	Clear debris from the inlet and clear 10m upstream of the culvert inlet, clear the outlet of the culvert. Landowner contacted and asked to carry out the works.
418	Eil Burn	Forest House, station Road.	13/03/2016	Clear screen and clear a section of the burn for 10m upstream from the screen, cut back all vegetation lying in or over the 10 m section.
420	Contullich Burn	Structure 60 and 100m upstream of structure 60	17/04/2016	Remove wind blown trees, woody debris, brown wheelie bin, and all litter, all items to be completely removed from the watercourse. A large tree trunk at structure 60 also requires removal.
421	Culchraggie Burn	Just upstream of the distillery reservoir	17/04/2016	Remove tree/bush lying across the burn the burn has the potential to flood the lower part of the Graveyard.
424	Benvraggie Burn	Wooded Area next to 9 Benbraggie Drive	24/02/2016	Clear all woody debris from the screen return burn bed to original depth clear a section of the watercourse from the screen 10m upstream. Land ownership being investigated.
434	Allt an Inbhir	Fassfern, Kinlocheil	29/04/2016	Wire fence collapsing into the burn is to beginning to collect debris. Landownership uncertain, enquiries ongoing.
437	River Peffery Trib 1	Behind Munro Sawmill	14/02/2016	Culvert inlet partially blocked. Cleared to allow flow during inspection but requires a further tidy up to remove remaining blockage material from apron area.
444	Raitts Burn	B9152 east of Kingussie	01/06/2016	Build up of gravel and sediment to be dredged from under road and within 10m upstream and downstream of culvert.
445	Gynack Burn	Spey Street	12/01/2016	Build up of gravel and sediment to be dredged from under road and upstream and downstream to railway.
447	Not Allocated	Insh House, Loch Insh	07/03/2016	Partial collapse of stone culvert where it joins a concrete pipe. Collapse to be repaired to allow further CCTV inspection.
449	Allt na Laitch	A862 near the Mineral Bridge	08/03/2016	Clear screen and clear a section of the burn for 5m upstream from the screen, cut back all vegetation lying in or over the 5m section.
450	River Peffery Trib 2	Footpath between Neil Gunn Road and Chestnut Road.	08/03/2016	Build up of gravel and sediment to be removed from the culvert inlet and 10m upstream. Clear debris from the culvert inlet.
451	River Peffery Trib3	Behind Ross Place and MacLeod Place.	08/03/2016	Clear silt, stones and vegetation from all the screens connected to the watercourse, cut back the vegetation in the swale, remove silt build up in the swale, clear the inlet area of the 680mm concrete culvert to expose the inlet.

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out