

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
216	Rhives Burn	Ben Braggie car park	04/09/2016	Remove debris and repair the collapsed culvert in the Ben Braggie car park. Landowner contacted and asked to carry out works.
267	Macrae Grove Burn	To the rear of 12 Macrae Grove	06/06/2016	Ditch at culvert inlet is overgrown causing partial blockage of the screen. Area immediately upstream of screen to be cut back and dead vegetation removed. Landowner contacted and asked to carry out works.
284	Mill Burn	Opposite 35 Harris Road	23/03/2017	Scottish Water sewer outfall headwall is partially collapsed into the watercourse. Headwall to be repaired. Scottish Water informed of works required.
296	Kinellan Burn	Adjacent to A834, upstream of St Anne's Episcopal Church	05/06/2016	New screen arrangement to be designed and installed at culvert inlet to replace existing damaged screen.
330	Ault na Skiah	Upper Slackbuie	22/06/2016	Woody debris to be removed from screen which is 80% blinded. Gravel deposits to be cleared from upstream side of screen also.
354	Lochalsh Burn 5	Kyle of Lochalsh	05/06/2016	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping upstream. Land ownership uncertain.
412	Ardival Burn	Culvert inlet near to the Ben Wyvis Hotel service entrance	06/07/2016	Clear debris from the inlet and clear 10m upstream of the culvert inlet, clear the outlet of the culvert. Landowner contacted and asked to carry out the works.
421	Culchraggie Burn	Just upstream of the distillery reservoir	06/07/2016	Remove tree/bush lying across the burn the burn has the potential to flood the lower part of the Graveyard.
424	Benvraggie Burn	Wooded Area next to 9 Benbhraggie Drive	06/06/2016	Clear all woody debris from the screen return burn bed to original depth clear a section of the watercourse from the screen 10m upstream. Land ownership being investigated.
434	Allt an Inbhir	Fassfern, Kinlocheil	28/10/2016	Wire fence collapsing into the burn is to beginning to collect debris. Landownership uncertain, enquiries ongoing.
447	Not Allocated	Insh House, Loch Insh	06/06/2016	Partial collapse of stone culvert where it joins a concrete pipe. Collapse to be repaired to allow further CCTV inspection.
451	River Peffery Trib3	Behind Ross Place and MacLeod Place.	03/08/2016	Clear silt, stones and vegetation from all the screens connected to the watercourse, cut back the vegetation in the swale, remove silt build up in the swale, clear the inlet area of the 680mm concrete culvert to expose the inlet.
454	Clachan Burn	Bettyhill	15/08/2016	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
461a	Dell Burn	Screen near to the A9 and the screen at Tesco Inches.	22/06/2016	Remove debris from screen locations on the Dell Burn
461b	Ault na Skiah	Screen at 144 Culduthel Road inverness	22/06/2016	Remove debris from screen.
462	Ault na Skiah	Castle Heather Park by B8082	05/07/2016	Silt trap is full and requires material to be removed.
466	Loch Eil Burn	Banavie Playpark at Neptunes Staircase.	06/06/2016	RegROUT internal cracks within manhole, dig down externally and reseal the external cracks, remove debris caught in the internal crack. Return ground to normal level.

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out