

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
216	Rhives Burn	Ben Braggie car park	04/09/2016	Remove debris and repair the collapsed culvert in the Ben Braggie car park. Landowner contacted and asked to carry out works.
284	Mill Burn	Opposite 35 Harris Road	23/03/2017	Scottish Water sewer outfall headwall is partially collapsed into the watercourse. Headwall to be repaired. Scottish Water informed of works required.
296	Kinellan Burn	Adjacent to A834, upstream of St Anne's Episcopal Church	01/01/2017	New screen arrangement to be designed and installed at culvert inlet to replace existing damaged screen.
330	Ault na Skiah	Upper Slackbuie	12/10/2016	Woody debris to be removed from screen which is 80% blinded. Gravel deposits to be cleared from upstream side of screen also.
354	Lochalsh Burn 5	Kyle of Lochalsh	03/09/2016	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping upstream. Land ownership uncertain.
412	Ardival Burn	Culvert inlet near to the Ben Wyvis Hotel service entrance	03/10/2016	Clear debris from the inlet and clear 10m upstream of the culvert inlet, clear the outlet of the culvert. Landowner contacted and asked to carry out the works.
421	Culchraggie Burn	Just upstream of the distillery reservoir	06/10/2016	Remove tree/bush lying across the burn the burn has the potential to flood the lower part of the Graveyard.
424	Benvraggie Burn	Wooded Area next to 9 Benbhraggie Drive	06/10/2016	Clear all woody debris from the screen return burn bed to original depth clear a section of the watercourse from the screen 10m upstream. Land ownership being investigated.
434	Allt an Inbhir	Fassfern, Kinlocheil	28/10/2016	Wire fence collapsing into the burn is to beginning to collect debris. Landownership uncertain, enquiries ongoing.
447	Not Allocated	Insh House, Loch Insh	06/06/2016	Partial collapse of stone culvert where it joins a concrete pipe. Collapse to be repaired to allow further CCTV inspection.
454	Clachan Burn	Bettyhill	15/08/2016	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
461a	Dell Burn	Screen near to the A9 and the screen at Tesco Inches.	30/10/2016	Remove debris from screen locations on the Dell Burn
461b	Ault na Skiah	Screen at 144 Culduthel Road inverness	30/10/2016	Remove debris from screen.
462	Ault na Skiah	Castle Heather Park by B8082	30/10/2016	Silt trap is full and requires material to be removed.
469	Parks Farm Burn	Screen between Miller Road and the Southern Distributer Road	02/12/2016	Upstream of the screen the bank is scouring away, place rock armour or gabion baskets in the area of scouring and reform the bank to the top of the screen. Looking downstream from the screen, on the left hand sidewall, voids are forming; these should be repaired by infilling with concrete and regrouting any cracks.
470	Abbots Place Burn	End of East Street, Beauly	31/08/2016	Remove all discarded vegetation and debris which has been cast aside from the screen at Shrewsbury House. Remove every 2nd bar from the top screen to reduce blinding of the top screen. Partially Complete.
473	Chapel Burn	Church Street Fortrose	22/08/2016	Cut back and remove vegetation up to 10m upstream from the screen. Dig out and remove all silt, stones and debris up to 10m upstream from the screen. Lift concrete lids to expose the silt trap and dig out/remove all silt stones and debris back down to invert level.
474	Allt na Churra	Screen at Ben Ard, Banavie	23/10/2016	Remove every second bar from the lower screen to allow smaller items of debris to pass through the screen .

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out