

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
296	Kinellan Burn	Adjacent to A834, upstream of St Anne's Episcopal Church	18/01/2022	New screen arrangement to be designed and installed at culvert inlet to replace existing damaged screen.
354	Lochalsh Burn 5	Kyle of Lochalsh	06/01/2022	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping upstream. Land ownership uncertain.
454	Clachan Burn	Bettyhill	06/01/2022	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
529	Knightswood Burn	A870 at the junction with Auchingale Place Watten.	19/08/2022	The Invert levels of the ditch have risen due to vegetation and silt deposition. Return ditch to original invert level to help mitigate flooding on to the roads.
532	Lochalsh Burn 4	Church Street, Kyle of Lochalsh	06/01/2022	Replace section of collapsed stone culvert with 400mm diameter pipe.
549	Scretan Burn Trib 3	Behind 1 Brinkman Terrace	06/01/2022	The culvert is blocked and requires clearing this is not an urgent job as there is an overflow channel
580	South Kessock Seawall	3 Areas in the seawall	06/01/2022	Repair missing stones sets in the seawall
608	Dingwall Flood Defences	Canal footpath At victoria park	26/01/2022	Infill and seal holes in the embankment where rabbits have been burrowing.
611	Dingwall Flood Defences	Canal footpath At victoria park	26/01/2022	Cut back and strim all vegetation growing in and along the flood embankment
621	Slackbuie Drain	Morninfield Road and Lillybank	02/02/2022	Landowner and factors to arrange remedial work following flooding in october 2020
624	Whaligoe Burn 1	Junction A99 road to Loch Watenan	15/08/2022	Remove blockage from within the road culvert. BEAR contacted and made aware of works required.
626	Mill Burn	Culvert under Sir Walter Scott Drive	06/01/2022	Remove all silt and stone deposition from the inlet and ditch 10m upstream from the inlet
627	Mill Burn	Harris Road Inverness	06/01/2022	Remove large tree which is lying in and across the burn
628	Druid Temple Burn	Druid Temple Crescent, Inverness	06/01/2022	Remove all silt and stone deposition from the inlet and ditch 10m upstream from the inlet
629	River Peffery	Docharty Road Dingwall	14/02/2022	Remove all large woody items from SSE service ducts
633	Druid Temple Burn	Next to the playing ground at Grebe Avenue Hall	26/01/2022	Remove all vegetation lying in and across the burn which is restricting forward flow of water
635	Ault na Skiah	Adjacent to the Distributor Road (B8082) behind properties on Castle Heather Avenue	26/01/2022	remove silt accumulations from the culvert inlet which has reduced the culvert width by approx 50%, please remove any self seeded trees that are growing in the burn or on the burn sides.
636	SWFRC	SWRFC numerous locations	18/12/2021	Remove all vegetation gorse/whin are growing on the crown and sides of the flood relief channel. Currently growing is numerous areas
640	Lochardil Burn	Behind Lochardil Rd/Macdonald Park	26/01/2022	Please remove large tree limb from watercourse and large limb hanging on another tree, please assess another large hazard beam which is caught within a Oak tree which stands above the garden of Lochardil Rd and remove if required.
641	Eil Burn	Behind Burnside Lane	02/02/2022	Remove vegetation along ditch. Priority increased following updated observation of increased weed growth.
644	Mill Burn	Behind Millburn Court	26/01/2022	Remove internal blockage within Left hand Culvert, specialist contractor may be required due to the confined space.

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out