

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
580	South Kessock Seawall	3 Areas in the seawall	20/01/2026	Repair missing stones sets in the seawall
626	Mill Burn	Culvert under Sir Walter Scott Drive	08/09/2025	Remove all silt and stone deposition from the inlet and ditch 10m upstream from the inlet
635	Ault na Skiah	Adjacent to the Distributor Road (B8082) behind properties on Castle Heather Avenue	02/09/2025	remove silt accumulations from the culvert inlet which has reduced the culvert width by approx 50%, please remove any self seeded trees that are growing in the burn or on the burn sides.
636	SWFRC	SWRFC numerous locations	03/09/2025	Remove all vegetation gorse/whin are growing on the crown and sides of the flood relief channel. Currently growing is numerous areas
658	Slackbuie Channel	Junction of Culduthel Road and Green Drive	02/09/2025	Silt accumulations and a build up of debris/rubbish at the culvert,some of which is lying at the twin culvert inlets, please remove as much silt as possible and ensure inlets are clear.
664	Ault na Skiah	Culvert outlet opposite Evan Barron Rd	08/09/2025	The culvert outlet is 50% surcharged due to windblown trees and woody debris lying across the watercourse for the majority of the open section down to the boundary fence of the property. Clear all woody debris from the open section.
724	Knockbain Burn	Knockbain Burn, near Gorstan, Dingwall	01/09/2025	Build up of Silt on LHS near Screen - Should be cleared
738	Holm Burn	Underneath Bridge on B862, near Holm Lodge. Inverness	08/09/2025	Tree Limb stuck underneath Bridge on B862. Limb will need to be removed.
741	Park Burn	Park Road,Sstrathpeffer	07/08/2025	Partial blockage and likely collapse of stone culvert within 2m of Manhole. Section is estimated to be below footpath. Callapse to be repaired and blockage removed.
743	Guisach Burn	Treasures of the Earth Museum	30/08/2025	Screen blinded by sediment. BEAR contacted to clear the screen.
744	Mill Burn	Section between Mason Road & Teal Avenue	08/09/2025	Fallen Trees lying within the Watercourse accumulating Derbis. Trees & Debris to be removed to ensure un-restricted flow.
748	Gergask Burn	Culvert under single track road near Am Bothan, Laggan	06/02/2026	Culvert Inlet blocked with Wooden debris & Large Tree Branch, should be removed to ensure un-restricted flow
749	Eil Burn	Screened Inlet to Culvert under Station Road (A862), Conon Bridge	30/10/2025	Inlet area silted up which has raised the bed of the watercourse, silting the Screen Inlet by approx. 50%. Silt should be removed surrounding the Inlet.
751	Culloden Burn West	Outlet of Culvert, next to Gruffalo carving	09/09/2025	Burn blocked with cluster of Woody debris, should be cleared to ensure un-restricted flow
754	Olrigh Cemetery Burn	Within Farm field east of St Trothan's Church, Olrigh Cemetery, Castletown	18/08/2025	Multiple fallen trees & concrete slabs lying within Burn D/S from Outlet, this should be cleared to ensure un-restricted waterflow. Section 18 letter issued
758	Culloden Burn West	Ferntower Avenue	15/08/2029	Jetting required to clear debris in culvert.
766	Ault Na Skiah	Upper Slackbuie, near Electricity Distribution Site, Inverness	02/09/2025	Screen 50% blocked with washed down stones & debris. Screen to be cleared.
773	Avoch Burn	Upstream from FB near Primary School	11/08/2025	Trees/ limbs have either snapped/ fallen into the burn. Trees should be removed
774	Bridge of Winless	Bridge Of Winless, Winless, Wick	18/08/2025	Piped Inlets on LHS & RHS of Bridge silted, should be ditched out to ensure unrestricted waterflow.
776	Alton Burn	3 Muircote Rd, Nairn	19/11/2025	Corrugated Iron Sheets from LHS wall lying in Watercourse, restricting waterflow. Should be re-installed/ replaced Section 18 Letter sent
777	Allt na Churra	Section of burn between Glenshian & Alt na Churra	26/11/2025	Garden clippings dimped in burn - Section 18 Letter sent
778	Swordale Burn	Ross Gardens, Bonar Bridge	28/10/2025	Section 18 Letter - Residents to remove dumped concrete blocks from Outlet area. Blocks have blocked the outlet.

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out