

**The Highland Council, Cairngorms National Park Authority & Scottish Natural Heritage
Undergrounding of Extra High Voltage Transmission Lines**

Contents

	Page
Executive Summary	1
Introduction	2
1 Review of the Issues	5
1.1 Background to the Proposed Beauly - Denny Upgrade	5
1.2 Transmission Circuit Technology	6
1.3 Cable Installation Considerations	15
1.4 Considerations for the Beauly-Denny Route	19
1.5 Review of the ICF Report and EC Background Paper	21
1.6 Update on Projects Mentioned in ICF Report and EC Background Paper	22
1.7 Additional Projects	26
1.8 UK EHV Cables in Sensitive Areas	28
2 Life Cycle Cost Calculations	31
2.1 Introduction	31
2.2 Capital Costs	31
2.3 Losses	36
2.4 Maintenance Costs	39
2.5 Availability & Reliability	39
2.6 Decommissioning Costs	45
2.7 Life Cycle Costs and Ratios	46
2.8 Comments on Aarhus - Aalborg Project Cost Data	48
2.9 Summary of Cost Issues	50
3 Environmental Impact Issues	51
3.1 Introduction	51
3.2 Land Use	51
3.3 Geology and Soils	52
3.4 Water Resources	53
3.5 Ecology and Nature Conservation	54
3.6 Landscape and Visual	57
3.7 Cultural Heritage	59
3.8 Air Quality	59
3.9 Traffic and Noise Vibration	60
3.10 Recreation, Community and Tourism Impacts	60
3.11 Ground reinstatement	62
3.12 Decommissioning	62
3.13 Summary of Environmental Impact Issues	62
4. Case Studies	68
4.1 Selection of the Case Studies	68
4.2 Beauly Case Study	70
4.3 Dalwhinnie Case Study	74
Summary and Conclusions	79
Overview & Introduction	79
Summary of Findings	80

**The Highland Council, Cairngorms National Park Authority & Scottish Natural Heritage
Undergrounding of Extra High Voltage Transmission Lines**

Figures	85
References	107
Glossary	109
Appendix 1 - Information Provided by SHETL	
Appendix 2 – Review of ICF and EC reports	
Appendix 3 – The Holford Rules	
Appendix 4 - Regulatory Issues	
Appendix 5 - Case Study Route Maps	
Appendix 6 – Aarhus - Aalborg Cost Data	
Appendix 7 – Capital Cost Data Provided	
Appendix 8 – Sample Life Cycle Cost Calculations (case studies)	
Appendix 9 – Summary of Reference 29 - Bird Strike Issues	
Appendix 10 – Photographs in the Area of the Beaully Case Study.	
Appendix 11 – Photographs in the Area of the Dalwhinnie Case Study.	