

# 4 What has been done to tackle the problem? (2)



1 Coarse debris screen, Tower Burn




2 Flow monitoring station, Tower Burn



3 Creation of step pools to protect against erosion



4 Channel restoration and headwall reinstatement (work in progress)



12 Numbers refer to photo locations



5 New coarse debris screen, Smithton Burn



6 New flow monitoring station, Smithton Burn



7 Restoration of the Smithton Burn at the site of the former care home



8 New coarse debris screen, Culloden Wood



9 Removal of inappropriate screen, Redburn Avenue



10 New, improved screen installation operating during 2014 floods.



11 New trash screen, Culloden Centre



12 Roadside drainage improvements to A96