## The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Abbots Place Burn End of East Street, Beauly 04/04/2017 top screen to reduce blinding of the top screen. Partially Complete.  Behind 3 Carn Efrig and between 19 & 20 07/05/2017 Remove all silt, stones and vegetation from the culvert outlets  Behind 3 Carn Efrig and between 19 & 20 07/05/2017 Remove all silt, stones and vegetation from the culvert outlets  Burn Place to Gladstone Avenue 14/02/2017 Jetting required to clear silt build up in culvert.  Foreshore of the River Ness. Upstream side of the dual carriageway near to the steps which lead down to the footpath. 05/04/2017 Release jammed hinges on the flap valve  Foreshore of the River Ness. Opposite John Clark House 05/04/2017 Release seized hinges on the flap valve  Brown Terrace Burn Kinlochleven 24/02/2017 Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.  Sold Balantoul Burn A82, Fort Augustus 26/04/2017 Clearance of sediment and vegetation from in front of flap valves and screen.  Sold Gladrum Burn Belford Road, Fort William 21/11/2017 Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  Whin Burn William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	Works Number	Watercourse Name	Location	Date for Re- Inspection*	Description of Works
Lochalsh Burn 5   Kyle of Lochalsh   10/04/2017   Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping upstream. Land ownership uncertain.			Adjacent to A834, upstream of St Anne's		
Clachan Burn   Bettyhill   16/02/2017   Build up of gravel and sediment to be removed, vegetation within watercourse to be removed	296	Kinellan Burn	Episcopal Church	03/07/2017	New screen arrangement to be designed and installed at culvert inlet to replace existing damaged screen.
Ault na Skiah Castle Heather Park by B8082 04/04/2017 Silt trap is full and requires material to be removed.  Remove all discarded vegetation and debris which has been cast aside from the screen at Shrewsbury House. Remove every 2nd bar fron top screen to reduce blinding of the top screen. Partially Complete.  Behind 3 Carn Elrig and between 19 & 20 Patterson Lane Behind 3 Carn Elrig and betwe	354	Lochalsh Burn 5	Kyle of Lochalsh	10/04/2017	Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping upstream. Land ownership uncertain.
Abbots Place Burn End of East Street, Beauly 04/04/2017 Remove all discarded vegetation and debris which has been cast aside from the screen at Shrewsbury House. Remove every 2nd bar from top screen to reduce blinding of the top screen. Partially Complete.  High Burnside Burn Patterson Lane 07/05/2017 Remove all silt, stones and vegetation from the culvert outlets  High Burnside Burn Burn Place to Gladstone Avenue 14/02/2017 Jetting required to clear silt build up in culvert.  Foreshore of the River Ness. Upstream side of the dual carriageway near to the steps which lead down to the footpath. 05/04/2017 Release jammed hinges on the flap valve  Foreshore of the River Ness. Opposite John Clark House 05/04/2017 Release seized hinges on the flap valve  Foreshore of the River Ness. Opposite John Clark House 05/04/2017 Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet. Clear and sediment of the culvert outlet. Surface of sediment and vegetation from in front of flap valves and screen.  Sof Alma Burn Belford Road, Fort William 21/11/2017 Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  Sof Gladdrum Burn High Street, Police Station, Fort William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	454	Clachan Burn	Bettyhill	16/02/2017	Build up of gravel and sediment to be removed, vegetation within watercourse to be removed
Abbots Place Burn End of East Street, Beauly 04/04/2017 top screen to reduce blinding of the top screen. Partially Complete.  Behind 3 Carn Elrig and between 19 & 20 07/05/2017 Remove all silt, stones and vegetation from the culvert outlets  Burn Place to Gladstone Avenue 14/02/2017 Jetting required to clear silt build up in culvert.  Foreshore of the River Ness. Upstream side of the dual carriageway near to the steps which lead down to the footpath. 05/04/2017 Release jammed hinges on the flap valve  Foreshore of the River Ness. Opposite John Clark House 05/04/2017 Release seized hinges on the flap valve  Foreshore of the River Ness. Opposite John Clark House 05/04/2017 Release seized hinges on the flap valve  Clark House 05/04/2017 Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.  Sold Balantoul Burn A82, Fort Augustus 26/04/2017 Clearance of sediment and vegetation from in front of flap valves and screen.  Sold Alma Burn Belford Road, Fort William 21/11/2017 Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  Sold Glasdrum Burn High Street, Police Station, Fort William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	462	Ault na Skiah	Castle Heather Park by B8082	04/04/2017	Silt trap is full and requires material to be removed.
High Burnside Burn Behind 3 Carn Elrig and between 19 & 20 Patterson Lane 07/05/2017 Remove all silt, stones and vegetation from the culvert outlets  Knockbain Burn Burn Place to Gladstone Avenue 144/02/2017 Jetting required to clear silt build up in culvert.  Foreshore of the River Ness. Upstream side of the dual carriageway near to the steps which lead down to the footpath.  Foreshore of the River Ness. Opposite John Clark House 05/04/2017 Release jammed hinges on the flap valve  Foreshore of the River Ness. Opposite John Clark House 05/04/2017 Release seized hinges on the flap valve  Brown Terrace Burn Kinlochleven 24/02/2017 Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.  Solution of the River Ness Opposite John Clark House 05/04/2017 Release seized hinges on the flap valve  Clearance of sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.  Clearance of sediment and vegetation from in front of flap valves and screen.  Solution of culvert to be cleared of debris/silt.  Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  Lundavra Road and A82 roundabout, Fort William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.					Remove all discarded vegetation and debris which has been cast aside from the screen at Shrewsbury House. Remove every 2nd bar from the
High Burnside Burn Patterson Lane 07/05/2017 Remove all silt, stones and vegetation from the culvert outlets  Knockbain Burn Burn Place to Gladstone Avenue 14/02/2017 Jetting required to clear silt build up in culvert.  Foreshore of the River Ness, Upstream side of the dual carriageway near to the steps which lead down to the footpath. 05/04/2017 Release jammed hinges on the flap valve  Foreshore of the River Ness. Opposite John Clark House 05/04/2017 Release seized hinges on the flap valve  497 River Ness Clark House 05/04/2017 Release seized hinges on the flap valve  498 Brown Terrace Burn Kinlochleven 24/02/2017 Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.  504 Balantoul Burn A82, Fort Augustus 26/04/2017 Clearance of sediment and vegetation from in front of flap valves and screen.  505 Alma Burn Belford Road, Fort William 21/11/2017 Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  506 Glasdrum Burn High Street, Police Station, Fort William 14/11/2017 Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  507 Whin Burn William Villiam 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	470	Abbots Place Burn	End of East Street, Beauly	04/04/2017	top screen to reduce blinding of the top screen. Partially Complete.
Burn Place to Gladstone Avenue   14/02/2017   Jetting required to clear silt build up in culvert.			Behind 3 Carn Elrig and between 19 & 20		
Foreshore of the River Ness. Upstream side of the dual carriageway near to the steps which lead down to the footpath.  Foreshore of the River Ness. Opposite John River Ness  Foreshore of the River Ness. Opposite John River Ness  Clark House  O5/04/2017  Release jammed hinges on the flap valve  Foreshore of the River Ness. Opposite John Release seized hinges on the flap valve  Release seized hinges on th	480	High Burnside Burn	Patterson Lane	07/05/2017	Remove all silt, stones and vegetation from the culvert outlets
the dual carriageway near to the steps which lead down to the footpath.    River Ness   Foreshore of the River Ness. Opposite John	484	Knockbain Burn	Burn Place to Gladstone Avenue	14/02/2017	Jetting required to clear silt build up in culvert.
River Ness lead down to the footpath. 05/04/2017 Release jammed hinges on the flap valve  Foreshore of the River Ness. Opposite John A97 River Ness Clark House 05/04/2017 Release seized hinges on the flap valve  499 Brown Terrace Burn Kinlochleven 24/02/2017 Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.  504 Balantoul Burn A82, Fort Augustus 26/04/2017 Clearance of sediment and vegetation from in front of flap valves and screen.  505 Alma Burn Belford Road, Fort William 21/11/2017 Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  506 Glasdrum Burn High Street, Police Station, Fort William 14/11/2017 Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  507 Whin Burn William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.			Foreshore of the River Ness. Upstream side of		
Foreshore of the River Ness. Opposite John A97 River Ness Clark House A98 Brown Terrace Burn Solution			the dual carriageway near to the steps which		
River Ness Clark House 05/04/2017 Release seized hinges on the flap valve  Brown Terrace Burn Kinlochleven 24/02/2017 Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.  Solution A82, Fort Augustus 26/04/2017 Clearance of sediment and vegetation from in front of flap valves and screen.  Bufford Road, Fort William 21/11/2017 Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  Glasdrum Burn High Street, Police Station, Fort William 14/11/2017 Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  Lundavra Road and A82 roundabout, Fort William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	496	River Ness	lead down to the footpath.	05/04/2017	Release jammed hinges on the flap valve
Brown Terrace Burn Kinlochleven 24/02/2017 Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.  504 Balantoul Burn A82, Fort Augustus 26/04/2017 Clearance of sediment and vegetation from in front of flap valves and screen.  505 Alma Burn Belford Road, Fort William 21/11/2017 Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  506 Glasdrum Burn High Street, Police Station, Fort William 14/11/2017 Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  507 Whin Burn William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.			Foreshore of the River Ness. Opposite John		
Balantoul Burn A82, Fort Augustus 26/04/2017 Clearance of sediment and vegetation from in front of flap valves and screen.  A82, Fort Augustus 26/04/2017 Clearance of sediment and vegetation from in front of flap valves and screen.  Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  Lundavra Road and A82 roundabout, Fort  William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	497	River Ness	Clark House	05/04/2017	
505 Alma Burn Belford Road, Fort William 21/11/2017 Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.  506 Glasdrum Burn High Street, Police Station, Fort William 14/11/2017 Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  507 Whin Burn William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	499	Brown Terrace Burn	Kinlochleven	24/02/2017	Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.
Glasdrum Burn High Street, Police Station, Fort William 14/11/2017 Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.  Lundavra Road and A82 roundabout, Fort William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	504	Balantoul Burn	A82, Fort Augustus	26/04/2017	Clearance of sediment and vegetation from in front of flap valves and screen.
Lundavra Road and A82 roundabout, Fort  Whin Burn  Lundavra Road and A82 roundabout, Fort  14/11/2017  Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	505	Alma Burn	Belford Road, Fort William	21/11/2017	Buried manhole needs to be uncovered and sections of culvert to be cleared of debris/silt.
507 Whin Burn William 14/11/2017 Section of culvert needs to be cleared of debris which was detected during CCTV Survey.	506	Glasdrum Burn	High Street, Police Station, Fort William	14/11/2017	Buried manholes need to be uncovered and section of culvert to be cleared of stones and leaves.
· ·			Lundavra Road and A82 roundabout, Fort		
Lundayra Road and Argyll Terrace Fort	507	Whin Burn	William	14/11/2017	Section of culvert needs to be cleared of debris which was detected during CCTV Survey.
Editad via rioda and riigyii roridoo, rori			Lundavra Road and Argyll Terrace, Fort		
508 Iona Burn William 18/11/2017 Sections of culvert to be cleared of high volume of debris/stones as identified during CCTV Survey.	508	Iona Burn	William	18/11/2017	Sections of culvert to be cleared of high volume of debris/stones as identified during CCTV Survey.
Junction of Lochaber Road and Zetland			Junction of Lochaber Road and Zetland		
Ashburn Avenue, Fort William 16/11/2017 Fixings of inlet screen to be replaced with new fixings. Leaves and branches sitting behind the screen to be cleared.	509	Ashburn	Avenue, Fort William	16/11/2017	Fixings of inlet screen to be replaced with new fixings. Leaves and branches sitting behind the screen to be cleared.

<sup>\*</sup> The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out