## The Highland Council: Scheduled Watercourse Maintenance Works - Pending

| Watercourse Name   | Location   | Date for Re-  | Description of Works  |
|--------------------|--|---|---|
| Number             |  | Inspection*   |   |
|                    | Adjacent to A834, upstream of St Anne's  |   |   |
| Kinellan Burn      | Episcopal Church   | 23/12/2017  | New screen arrangement to be designed and installed at culvert inlet to replace existing damage   |
| Lochalsh Burn 5    | Kyle of Lochalsh   | 24/04/2018  | Footbridge Culvert has partially collapsed restricting flow in the burn and causing overtopping up  |
| Clachan Burn       | Bettyhill  | 15/08/2018  | Build up of gravel and sediment to be removed, vegetation within watercourse to be removed  |
| Ault na Skiah      | Castle Heather Park by B8082   | 05/02/2018  | Silt trap is full and requires material to be removed.  |
|                    | Behind 3 Carn Elrig and between 19 & 20  |   |   |
| High Burnside Burn | Patterson Lane   | 12/12/2017  | Remove all silt, stones and vegetation from the culvert outlets   |
| Knockbain Burn     | Burn Place to Gladstone Avenue   | 18/03/2018  | Jetting required to clear silt build up in culvert.   |
| Rainbow Burn       | Bruce Gardens, Fortrose  | 24/05/2018  | Sections of culvert to be cleared of roots.   |
|                    | Junction of Lower Wards and E Watergate,   |   |   |
| 513 Kings Burn     | Fortrose   | 24/05/2018  | Section of culvert to be cleared of roots.  |
|                    | A870 at the junction with Auchingale Place   |   | The Invert levels of the ditch have risen due to vegetation and silt deposition. Return ditch to orig   |
| Knightswood Burn   | Watten.  | 16/02/2018  | roads.  |
| Lochalsh Burn 4    | Church Street, Kyle of Lochalsh  | 18/03/2018  | Replace section of collapsed stone culvert with 400mm diameter pipe.  |
| 533 Alma Burn      | Behind Fort William Leisure Centre   | 29/12/2017  | Replace chamber lids which have been dumped into the chamber. If lids are damaged then insta  |
|                    |  |   | Remove all vegetation and silt and stones which have accumulated infront of the screen, clear the   |
| Allt na Laitch     | A862 prior to the Mineral Bridge   | 12/12/2017  | will allow any silt which has accumulated within the culvert to wash out  |
|                    | Lochalsh Burn 5<br>Clachan Burn<br>Ault na Skiah<br>High Burnside Burn<br>Knockbain Burn<br>Rainbow Burn<br>Kings Burn<br>Knightswood Burn<br>Lochalsh Burn 4<br>Alma Burn<br>Allt na Laitch | Adjacent to A834, upstream of St Anne'sKinellan BurnEpiscopal ChurchLochalsh Burn 5Kyle of LochalshClachan BurnBettyhillAult na SkiahCastle Heather Park by B8082Behind 3 Carn Elrig and between 19 & 20High Burnside BurnPatterson LaneKnockbain BurnBurn Place to Gladstone AvenueRainbow BurnBruce Gardens, FortroseJunction of Lower Wards and E Watergate,<br>FortroseKnightswood BurnA870 at the junction with Auchingale PlaceKnightswood BurnBehind Fort William Leisure CentreAllt na LaitchA862 prior to the Mineral Bridge | Watercourse NameLocationInspection*Adjacent to A834, upstream of St Anne'sEpiscopal Church23/12/2017Lochalsh BurnEpiscopal Church23/12/2017Lochalsh Burn 5Kyle of Lochalsh24/04/2018Clachan BurnBettyhill15/08/2018Ault na SkiahCastle Heather Park by B808205/02/2018High Burnside BurnPatterson Lane12/12/2017Knockbain BurnBurn Place to Gladstone Avenue18/03/2018Rainbow BurnBruce Gardens, Fortrose24/05/2018Junction of Lower Wards and E Watergate,<br>FortroseFortrose24/05/2018Knightswood BurnWatten.16/02/2018Lochalsh Burn 4Church Street, Kyle of Lochalsh18/03/2018Alma BurnBehind Fort William Leisure Centre29/12/2017 |

\* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out

aged screen. upstream. Land ownership uncertain.

original invert level to help mitigate flooding on to the

nstall replacements.

r the culvert outlet to a point 10m downstream this