Agenda item	11.1
Report	HLC/034/22
no	

THE HIGHLAND COUNCIL

Committee: THE HIGHLAND LICENSING COMMITTEE

Date: 20 June 2022

Report title: Taxi Operator's licence – Pawel Wyderka (Ward 14 –

Inverness Central)

Report by: Principal Solicitor – Regulatory Services

Purpose/Executive summary

1.1 Summary

1.

This report relates to a licensed taxi operator who has been reported for a breach of licence conditions.

This item is subject to a formal hearing procedure.

2. Recommendation

2.1 Members are asked to determine in accordance with the Council's hearings procedure, whether the licence holder continues to be a fit and proper person to hold a taxi operators' licence and/or whether the carrying out of the activity to which the licence relates is likely to cause a threat to public safety. Upon determining this, members are asked to decide whether any action should be taken against the licence holder.

3. Background

3.1 The Highland Council has resolved that in terms of the Civic Government (Scotland) Act 1982 (the "Act") a licence will be required for the operation of a taxi. A licence for the same is issued by the Highland Council and is valid for the whole Council area.

4. Licence Holder

4.1 Pawel Wyderka is a licensed taxi operator. His licence expires on 16 June 2024.

5. Highland Council Penalty Points System for Taxi and Private Hire Operators

- 5.1 Highland Council (Trading Standards) introduced a Penalty Points System on 01 July 2006 to assist in the assessment of the level of compliance shown by each operator in relation to conditions 1 and 2 of a taxi operator's licence. When the points on an operator's licence reach 20 or more during a two year rolling period, the operator becomes the subject of a report to the Highland Licensing Committee.
- 5.2 On 5 May 2022 a report in relation to Mr Wyderka was received from the Council's Trading Standards Service who are responsible for the enforcement of the licensing scheme for taxi/private hire cars and their drivers. A copy of the report received from Trading Standards is attached as Appendix 1, together with copies of productions which are attached as Appendix 2.
- 5.3 The report has been submitted due to Mr Wyderka accruing a total of 37 points on taxi Operator Licence no. 11 785 and for failing to maintain his licensed taxi to the standards required by the Licensing Authority.

6 Process

6.1 A copy of the report and all attachments have been sent to Mr Wyderka who has been invited to attend and will be provided with an opportunity to be heard by the Committee. A copy of the procedure which will be followed at the meeting has also been sent to Mr Wyderka.

7. Consideration of action to be taken

- 7.1 In terms of Section 11 of Schedule 1 of the Civic Government (Scotland) Act 1982 a Licensing Authority may suspend a licence(s) on the following grounds:
 - (a) if in their opinion the holder of the licence is no longer a fit and proper person to hold the licence(s):
 - (b) the carrying on of the activity to which the licence relates has caused, is causing or is likely to cause undue public nuisance or a threat to public order or public safety;
 - (c) a condition of the licence has been contravened.
- **7.2** If Members are not of a mind to suspend the licence, the Committee could require the operator to present his vehicle for inspection on a more frequent period than the current 6 or 12 months inspection regime eg every 3 months. This would allow Trading Standards an opportunity to undertake more regular monitoring of the vehicle.

8. Policies and Conditions

8.1 The standard taxi operator's licence conditions are relevant to this case and can be accessed via the following link:

https://www.highland.gov.uk/downloads/file/3516/taxi operator conditions of licence

8.2 In terms of condition 1 of the taxi operator's licence conditions, "the holder of a taxi operator's licence shall ensure that the taxi, including all body work, upholstery and fittings, is maintained in a safe and serviceable condition and, subject to prevailing road conditions, is in a clean condition and of smart appearance".

9. Implications

9.1 Not applicable.

Date: 19 May 2022

Author: Michael Elsey

Appendix 1: Trading Standards report

Appendix 2: Trading Standards copies of productions

CIVIC Government (Scotland) Act 1982

Penalty Points System for Licensed Taxi and Private Hire Car (PHC) Operators and Drivers

Reference No TS/CG(S)/APP/110785

Against: Pawel Wyderka Age: DOB:

Address

Licence Held: Taxi Operators Licence 11 0785

Expiration Date: 16/06/2024

Vehicle description: Ford Galaxy VRM: ST13 VAY

Date of first registration: 02/08/2013

Mileage at last inspection: 143226

Penalty Points Total as of 20/04/2022: 37 Points

Reporting Officer: Bobby Smeaton

Designation: Enforcement Officer

Address: Highland Council

Trading Standards

38 Harbour Road

Inverness

IV1 1UF

Telephone Number: 01463 644574

It is reported that:

Mr Wyderka has failed to maintain his licensed Taxi to the standard required by the Licensing Authority, Highland Council, contrary to condition 1 of the Taxi Operator's Conditions of Licence, as demonstrated by the result of three vehicle inspections, carried out by The Council's approved contractor.

Background Information

The penalty points system was introduced on 1st July 2006. Its purpose is to assist Trading Standards in the evaluation of how well licensed operators maintain their vehicles.

Points accumulate when faults are found at the Council's inspection of licensed vehicles or during 'on the spot' inspections by Trading Standards Staff. An appeal system is in place, which allows an Operator to question the allocation of points.

When the points total reaches 20 or more during a two-year rolling period, the Operator becomes the subject of a report to the Licensing Committee.

(Production Number 1. Penalty points tariff).

Summary of Facts and Evidence

This report relates to the licensed vehicle operated by PAWEL WYDERKA licence number 11 0785. The vehicle on this licence is a Ford Galaxy, vehicle registration mark ST13 VAY. The licence has accrued 37 penalty points since 4th March 2021, for faults identified during three inspections of the licenced vehicle, carried out by the Council's contractor. This matter is reported because the licence has accumulated more than 20 points within a two-year rolling period.

Antecedents

Mr Wyderka currently holds Taxi operator's licence 11 0785 which was renewed on 17/06/2021 and is valid until 16/06/2024. The present vehicle is the fifth vehicle to be operated on this licence.

Evidence relating to licence 11 0785

Inspection by the council's contractor of the licensed vehicle on 4th March 2021 resulted in a failure with four faults being identified:

Nearside parking brake has no effort

Nearside parking brake cable broken at calliper

Parking brake efficiency below requirements

Exhaust emissions exceed manufacturer's specified limit (0.51)

This failure accrued 10 penalty points.

In the opinion of the examiner, the vehicle was deemed dangerous to drive because of the defects listed.

(Production number 2. Taxi test report form dated 04/03/21).

A suspension notice in terms of Section 11 of the Civic Government (Scotland) Act 1982, was issued to Mr Wyderka via e mail.

(Production Number 3. Suspension notice dated 04/03/21)

The vehicle was presented for re-test on 05/03/21 but failed again with the following fault:

Exhaust emissions exceed manufacturer's specified limit (0.51)

*please note the re-test does not attract penalty points as the licence to operate the vehicle has already been suspended.

(Production Number 4. Taxi test report form dated (05/03/21)

The vehicle was retested on 12th March 2021 and passed the inspection.

(Production Number 5. Taxi test report form dated 12/03/21).

A warning letter in terms of Penalty Points System and the Civic Government (Scotland) Act 1982, was sent to Mr Wyderka via email.

(Production Number 6. Warning Letter dated 10/04/21)

On 9th September 2021, the vehicle was subjected to its 6 monthly inspection carried out by the council's contractor. This inspection resulted in a failure. The fault identified was:

Nearside rear handbrake not working

For this fault the operator was issued 5 penalty points and now had a total of 15 points on his operator's licence accrued within the two-year rolling period.

(Production Number 7. Taxi test report dated 09/09/21)

A suspension notice in terms of Section 11 of the Civic Government (Scotland) Act 1982, was issued to Mr Wyderka via e mail.

(Production Number 8. Suspension notice dated 09/09/21)

The vehicle was retested on the 10th September 2021 and attained a pass.

(Production Number 9. Taxi test report dated 10/09/21)

The vehicle was again due its 6 monthly inspection and on 9th March 2022 was presented for inspection but failed with the following defects:

Emissions above limits

Fuel cap missing

Handbrake readings below limits

Service brake below limits

Both rear axle front bushes perished

o/s headlight too high

No rubber on brake pedal

First aid kit expired (2021)

For these faults Mr Wyderka was given 22 penalty points which took him to a total of 37 within the 2-year rolling period.

(Production Number 10. Taxi test report dated 09/03/22)

A suspension notice in terms of Section 11 of the Civic Government (Scotland) Act 1982, was issued to Mr Wyderka via e mail.

(Production Number 11. Suspension notice dated 09/03/21)

The vehicle was re-tested on the 21st March 2022 and passed.

(Production number 12. Taxi test report dated 21/03/22)

Current operating protocols of the penalty points system require that when an Operator reaches 20 or more points, they are interviewed by Trading Standards Staff, to ascertain if there is any reason that points should not have been allocated to the licence prior to being reported to the Licensing Committee.

Trading Standards Staff interviewed Mr Wyderka on 11th April 2022. He was duly notified that the points on his Taxi operator's licence had exceeded the threshold and asked if he had any mitigating circumstances for this. Mr Wyderka did not have any mitigating circumstances and had not had the vehicle checked over by a suitable garage prior to submitting the vehicle for its taxi inspection. He was therefore informed that the matter would be reported to the licensing committee for their consideration.

Evidence held by Trading Standards:

Number	Description
1	Penalty Points Tariff
2	Taxi test report 04/03/2021
3	CG(S)A S11 suspension notice 04/03/2021
4	Taxi test report 05/03/2021
5	Taxi test report 12/03/2021
6	10pt warning letter 10/04/2021
7	Taxi test report 09/09/2021
8	CG(S)A S11 suspension notice 09/09/2021
9	Taxi test report 10/09/2021
10	Taxi test report 09/03/2022
11	CG(S)A S11 suspension notice 09/03/2022
12	Taxi test report 21/03/2022



Trading Standards Business Guidance

Taxi & PHC Penalty Points System

This leaflet is designed to explain the penalty points system in operation within Highland Council and provide basic guidance to Taxi and PHC operators and drivers on its use. It is not a complete or an authoritative statement of the law relating to taxi and PHC businesses.

1. What is it?

1.1. The Penalty Points System (the system) is an evaluation tool used by Trading Standards staff to determine whether the licensed vehicle of a Taxi/PHC operator or driver, when examined over a period of time, has reached a point where the matter justifies referral to the Licensing Committee.

2. Why was it introduced?

- 2.1. The system was introduced in 2006 following concerns expressed by Members of the Civic Government Licensing Working Group about the level of safety related failures recorded during the routine vehicle examinations undertaken by the Council's appointed contractor.
- 2.2. In addition to the real public safety concerns that existed, the time spent by Trading Standards staff suspending unsafe vehicles from use and chasing up licensees to remedy other defects found, was seen as wasteful and inefficient.
- 2.3. Trading Standards have used the system since then to maintain the general standard of Taxi's and PHC's operating within Highland.

3. What is the principle of the system?

- 3.1. The system is a way of demonstrating to licensees any failures to maintain and otherwise operate a licensed vehicle, including unacceptable actions or omissions by a licensed driver. The system encourages self-regulation and by routine scrutiny provides a fair process for all licensed operators/drivers.
- 3.2. In addition, it provides a clear decision making process for Trading Standards staff to report a matter to the Licensing Committee. The system can be seen as being fair and transparent. Members can also be confident that a consistent approach is being taken and that the behaviour of one licensee can be easily compared against that of other licensees as well as against the standard set by the Council.

4. How does it work in practice?

- 4.1. The current Penalty Points Tariff is annexed to this document. The tariff was drawn up by reference to existing DVSA guidelines on the categorisation of vehicle safety defects. Other non-safety elements of the tariff were agreed by the Civic Government Licensing Working Group members.
 - 4.1.1. The tariff was last reviewed by the Civic Government Licensing Working Group during 2009.
- 4.2. Different categories of licence holder will be liable to have Penalty Points allocated for different events or defects found. This is due to the very specific responsibilities that are applicable to licence categories; examples of this are as follows: -

4.2.1. A licensed Operator has overall responsibility for the vehicle and will therefore be liable for safety defects discovered which should have been detected by appropriate routine maintenance.

A licensed driver also has some responsibility for the safety of the vehicle, but whilst it is seen as reasonable that he/she should carry out an examination of the vehicle at the start of a shift and detect tyres that are below the legal tread depth, he/she is not liable for defects which would take a mechanic to identify.

- 4.2.2. A licensed operator cannot be liable for the failure of a licensed driver to display his identity badge. In such circumstances penalty points will only be allocated to the driver.
- 4.2.3. In some cases e.g. the "bald tyres" scenario, both driver and operator would be allocated penalty points as both have equal liability.
- 4.3. Vehicle defects are recorded on the Trading Standards database. These include defects discovered during:
 - Routine Council examinations
 - inspections carried out on taxi ranks and elsewhere while vehicles are in use
 - complaint investigations, and
 - any necessary follow-up actions e.g. warnings issued where remedial work has not been carried out as required.

This record entry is automatically translated into the relevant number of Penalty Points according to the agreed tariff.

4.4. A licensee can appeal to Trading Standards operational staff against the allocation of penalty points and, in cases where circumstances justify, an adjustment to the allocated points will be made.

A further route of appeal to the Trading Standards Team Leader is also available, should this be necessary.

5. What is the Formal Action Trigger Point?

- 5.1. The "Formal Action Trigger Point" has been set at a total of 20 Penalty Points during any 2 year period.
- 5.2. If any licensee accumulates 10 points or more they will be formally notified in writing of this fact and given the opportunity to discuss the matter with a member of Trading Standards staff.
- 5.3. Where the "Formal Action Trigger Point" is reached or exceeded, the preparation of a report to the Licensing Committee will be triggered.
- 5.4. Licensees are then notified in full of the faults or problems which have led to the penalty points accumulated and are given the opportunity, before the report is submitted, to make representations to the Trading Standards Manager in relation to the matter.
- 5.5. A report would only go ahead if the Trading Standards Manager is content that such a report is justified.

6. What information will the report to the Licensing Committee contain?

6.1. The report will identify the licensee to which the case relates. This could be a licensed operator, licensed driver or both.

- 6.2. Where a report is made against a licensed operator who is also a driver, the report may only be in relation to one of the licences he/she currently possesses.
- 6.3. The Penalty Points accumulated by the licence will be identified, as will the full facts including vehicle inspection reports, complaint outcomes, warnings issued and any other evidence relevant to the case. It is on the basis of the total evidence and not simply on the Penalty Points total that the case will be submitted.

Annex: Penalty Points Tariff

Operator		Applic	ability				Defect		Penalty
Taxi	Ope			ver	Category	Sub-		Code	
✓ ✓	_		Taxi	PHC		Category	•		
✓ Safety Tyres/Wheels Routine Maintenance Med Risek / Undetectable by Routine Maintenance Part Routine Maintenance TAS 5 ✓ ✓ Safety Brakes High Risk / Detectable by Routine Maintenance TAS 2 ✓ ✓ Safety Brakes High Risk / Detectable by Routine Maintenance TB7 7 ✓ ✓ Safety Steering / Suspension Med Risk / Undetectable by Routine Maintenance TC7 7 ✓ ✓ Safety Steering / Suspension High Risk / Detectable by Routine Maintenance TC7 7 ✓ Safety Steering / Suspension Med Risk / Undetectable by Routine Maintenance TC2 2 ✓ Safety Steering / Suspension Med Risk / Undetectable by Routine Maintenance TC2 2 ✓ Safety General High Risk / Detectable by Routine Maintenance TC2 2 ✓ Safety General High Risk / Obvious TD7 7 ✓ Safety Lighting High Risk / Obvious TD7 7 ✓ Safety					Safety		High Risk / Obvious	TA7	7
	✓	✓					Med-High Risk / Detectable by	TA5	5
							Routine Maintenance		
✓ ✓ Safety Brakes High Risk / Debouous TB7 7 ✓ ✓ Safety Brakes Med-High Risk / Detectable by Routine Maintenance TB5 5 ✓ ✓ Safety Steering / Suspension Med Risk / Undetectable by Routine Maintenance TC7 7 ✓ ✓ Safety Steering / Suspension Med-High Risk / Detectable by Routine Maintenance TC5 5 ✓ Safety Steering / Suspension Med Risk / Undetectable by Routine Maintenance TC2 2 ✓ Safety General General High Risk / Detectable by Routine Maintenance TD5 5 ✓ Safety Lighting Med Risk / Undetectable by Routine Maintenance TD5 5 ✓ Safety Lighting Med Risk / Undetectable by Routine Maintenance TE5 5 ✓ Safety Lighting Med Risk / Undetectable by Routine Maintenance TE5 5 ✓ Safety Lighting Med Risk / Undetectable by Routine Maintenance TE5 5 ✓ Doc	✓	✓			Safety	Tyres/Wheels	Med Risk / Undetectable by	TA2	2
Y							Routine Maintenance		
Safety Safety Steering / Suspension Safety Steering / Suspension Safety Steering / Suspension Steering / Suspe	✓	✓	✓	✓	Safety	Brakes	High Risk / Obvious	TB7	7
✓ ✓ Safety Brakes Med Risk / Undetectable by Routine Maintenance TB2 2 ✓ ✓ Safety Steering / Suspension High Risk / Obvious TC7 7 ✓ ✓ Safety Steering / Suspension Med-High Risk / Detectable by Routine Maintenance TC5 5 ✓ ✓ Safety General General High Risk / Detectable by Routine Maintenance TC7 7 ✓ ✓ Safety General General High Risk / Obvious TD7 7 ✓ ✓ Safety General General High Risk / Obvious TD7 7 ✓ ✓ Safety General General High Risk / Obvious TD7 7 ✓ ✓ Safety General General High Risk / Obvious TD7 7 ✓ ✓ Safety Lighting High Risk / Obvious TD7 7 ✓ ✓ Safety Lighting Med-High Risk / Obvious TD5 5 V ✓ <t< td=""><td>✓</td><td>✓</td><td></td><td></td><td>Safety</td><td>Brakes</td><td>Med-High Risk / Detectable by</td><td>TB5</td><td>5</td></t<>	✓	✓			Safety	Brakes	Med-High Risk / Detectable by	TB5	5
Safety Steering / Suspension Safety Steering / Suspension Safety Steering / Suspension Safety Steering / Suspension Steering / Suspension Sus							Routine Maintenance		
✓ ✓ Safety Steering / Suspension High Risk / Obvious TC7 7 ✓ ✓ Safety Steering / Suspension Med-High Risk / Detectable by Routine Maintenance TC5 5 ✓ ✓ Safety General General Routine Maintenance Med-High Risk / Detectable by Routine Maintenance TD7 7 ✓ ✓ Safety General Routine Maintenance Med-High Risk / Detectable by Routine Maintenance TD5 5 ✓ ✓ Safety Lighting High Risk / Devious TD7 7 ✓ ✓ Safety Lighting High Risk / Detectable by Routine Maintenance TD2 2 ✓ ✓ Safety Lighting High Risk / Devious TE7 7 ✓ ✓ Safety Lighting High Risk / Detectable by Routine Maintenance TE5 5 ✓ Safety Lighting High Risk / Devious TE7 7 ✓ Safety Lighting High Risk / Devious TE5 5 Factor Bafety Mod Risk / Undetectable by Routine Maintenance	✓	✓			Safety	Brakes	Med Risk / Undetectable by	TB2	2
Safety Steering / Suspension Routine Maintenance Safety Steering / Suspension Routine Maintenance Safety Steering / Suspension Routine Maintenance Well Risk / Undetectable by TC2 2 Safety General High Risk / Obvious TD7 7 Safety General Med-High Risk / Obvious TD7 5 Routine Maintenance TD7 5 Safety Lighting Routine Maintenance TE7 7 Safety Lighting Med-High Risk / Detectable by TE5 5 Routine Maintenance TE7 7 Safety Lighting Med-High Risk / Detectable by TE5 5 Routine Maintenance TE7 7 Safety Lighting Med-High Risk / Detectable by TE5 5 Routine Maintenance TE7 7 Safety Lighting Med Risk / Undetectable by TE5 5 Routine Maintenance TE7 7 Safety Lighting Med Risk / Undetectable by TE5 5 Routine Maintenance TE7 7 Safety Lighting Med Risk / Undetectable by TE5 5 Routine Maintenance TE7 7 Routine Maintenance TE7 7 Not Present (Insurance Valid) TE1 1 Documents, etc. Documents, etc. Documents, etc. Document V5 Documents, etc. Documents, etc							Routine Maintenance		
✓ Safety Steering / Suspension Med-High Risk / Detectable by Suspension TC5 5 ✓ ✓ Safety Steering / Suspension Med Risk / Undetectable by Routine Maintenance TC2 2 ✓ ✓ ✓ Safety General General General High Risk / Districtable by Routine Maintenance TD7 7 ✓ ✓ Safety General General General General Routine Maintenance Med-High Risk / Detectable by Routine Maintenance TD5 5 ✓ ✓ Safety Lighting High Risk / Districtable by Routine Maintenance TE5 5 ✓ ✓ Safety Lighting Routine Maintenance Med Risk / Undetectable by Routine Maintenance TE5 5 ✓ ✓ Safety Lighting Routine Maintenance Med Risk / Undetectable by Routine Maintenance TE2 2 2 ✓ ✓ Documents, etc. Insurance Not Present (MOT Valid) TF2 2 2 ✓ ✓ Documents, etc. Registration Document Vs. Not Present (MOT Valid) TG2 1 ✓	✓	✓	✓	✓	Safety		High Risk / Obvious	TC7	7
Suspension									
✓ Safety Steering / Suspension Med Risk / Undetectable by Routine Maintenance TC2 2 ✓ ✓ Safety General General Mulph Risk / Obvious TD7 7 ✓ ✓ Safety General Routine Maintenance High Risk / Obvious TD7 7 ✓ ✓ Safety Lighting Routine Maintenance Med High Risk / Obvious TE7 7 ✓ ✓ Safety Lighting Routine Maintenance TE7 7 ✓ ✓ Safety Lighting Routine Maintenance TE5 5 ✓ Documents, etc. MoDT Mot Present (Insurance Valid) TE1 1 ✓ Documents, etc. Registration Document VS Not Present (MOT Valid) TG2 1 ✓ Documents, etc. Documents,	✓	✓			Safety			TC5	5
Suspension Southy Suspension Routline Maintenance TD7 TD									
✓ ✓ ✓ Safety General High Risk / Obvious TD7 7 ✓ Safety General Med-High Risk / Detectable by Routine Maintenance TD5 5 ✓ Safety General Routine Maintenance Med Risk / Undetectable by Routine Maintenance TD2 2 ✓ ✓ Safety Lighting Lighting Med-High Risk / Obvious TE7 7 ✓ Safety Lighting Risk / Obvious TE7 7 Med Risk / Undetectable by Routine Maintenance TE7 7 Well All All All All All All All All All	✓	✓			Safety		1	TC2	2
Safety General Med-High Risk / Detectable by Routine Maintenance Safety General Med Risk / Undetectable by TD2 2 Routine Maintenance A Safety Lighting High Risk / Obvious TE7 7 Safety Lighting High Risk / Detectable by Routine Maintenance Lighting Med-High Risk / Detectable by Routine Maintenance Lighting Med-High Risk / Detectable by Routine Maintenance Safety Lighting Med Risk / Undetectable by Routine Maintenance Safety Lighting Med Risk / Undetectable by Routine Maintenance Not Present (Insurance Valid) TF1 1 Documents, etc. Documents, etc. Document V5 Registration Document V5 Safety Registration Not Present (MOT Valid) TG2 1 Tariff Card Not Present / Illegible TJ3 3 Tariff Card Not Present / Illegible TJ3 3 Tariff Card Not Present / Illegible TK3 3 Card Documents, etc. Documents, etc. Documents, etc. Documents, etc. Tariff Card Not Present / Illegible TK3 3 TK5 5 TK									
Routine Maintenance File Routine Maintenance File Routine Maintenance File File Routine Maintenance File Routine Maintenance File File Routine Maintenance File File Routine Maintenance File File File Routine Maintenance File File File Routine Maintenance File File File File Routine Maintenance File File File File File Routine Maintenance File File File File File Routine Maintenance File File File File File File Routine Maintenance File Routine Maintenance File Routine Maintenance File			✓	√					
Safety General Med Risk / Undetectable by Routine Maintenance	✓	✓			Safety	General		TD5	5
Routine Maintenance									
✓ ✓ Safety Lighting High Risk / Obvious TE7 7 ✓ Safety Lighting Med-High Risk / Detectable by Routine Maintenance TE5 5 ✓ Safety Lighting Med Risk / Undetectable by Routine Maintenance TE2 2 ✓ Documents, etc. Insurance Not Present (Insurance Valid) TF1 1 ✓ Documents, etc. Registration Document V5 Not Present (MOT Valid) TG2 1 ✓ Documents, etc. Registration Document V5 Not in operators name TH1 1 1 ✓ Documents, etc. Tariff Card etc. Not Present TI1 1 1 ✓ Documents, etc. Drivers ID Card Not Present TK5 5 5 ✓ Documents, etc. Drivers ID Card Incorrectly Displayed TK3 3 3 3 3 4 1 1 1 4 4 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 7 7	✓	✓			Safety	General	-	TD2	2
Safety Lighting Med-High Risk / Detectable by Routine Maintenance Safety Lighting Med Risk / Undetectable by Routine Maintenance Med Risk / Undetectable by TE2 2 Routine Maintenance Not Present (Insurance Valid) TF1 1 etc. Documents, etc. Documents, etc. Documents, etc. Documents, etc. Document V5 Fegistration Document V5 Fegistration Pocument V5 Fegistration Pocument V5 Ferificed Not Present (MOT Valid) TG2 1 TT1 1									
Safety Lighting Med Risk / Undetectable by Routine Maintenance V V Documents, etc. V Documents, etc. Documents, etc. Document V5 Pocument V5 Document V5 Pocument V5 Pocuments, etc. Pocument V5 Poc			✓	√					
Safety	√	✓			Safety	Lighting		TE5	5
Routine Maintenance Routine Maintenate (Not Present (Insurance Valid) Routine Maintenance Routine Maintenante Registration Not Present Registration Not Present / Illegible Thi 1 Routine Maintenance Routine Maintenance Registration Not Present Incorrectly Displayed Tha 3 Routine Maintenance The 1 Routine Maintenance Routine Maintenance Routine Maintenance The 1 Routine Maintenance The 1 Incorrectly Displayed Tha 3 Routine Maintenan									_
✓ ✓ Documents, etc. Insurance etc. Not Present (Insurance Valid) TF1 1 ✓ ✓ Documents, etc. MOT Not Present (MOT Valid) TG2 1 ✓ ✓ Documents, etc. Registration Document V5 Not in operators name TH1 1 ✓ ✓ Documents, etc. Registration Document V5 Not Present TI1 1 ✓ ✓ Documents, etc. Tariff Card etc. Not Present / Illegible TJ3 3 ✓ ✓ Documents, etc. Drivers ID Card Incorrectly Displayed TK3 3 ✓ ✓ Documents, etc. Licence plate etc. Not Present TL5 5 ✓ ✓ Documents, etc. Documents, etc. Incorrectly Displayed TL3 3 ✓ ✓ Documents, etc. Documents, etc. Displayed TL3 3 ✓ ✓ Documents, etc. Documents, etc. Displayed TL3 3 ✓ ✓ Taximeter Meter Unsealed (Not 'False or Unjust' and with Reasonable Excuse) TN	✓	✓			Safety	Lighting		TE2	2
etc. Documents, etc. Document V5 Person Not Present (MOT Valid) Person Not In operators name Person Not Present (MOT Valid) TG2 1 Person Not In operators name TH1 1 Person Not Present IIII 1 Person Not Present / Incorrectly Displayed III 1 Person Not Present / Incorrectly III 1 Person Not Present / Incorrectly Displayed III 1 Person Not Present / Incorrectly III 1 Person Not Present /									
Documents, etc. Document V5 Document V5 Document V5 Present (MOT Valid) TG2 1	✓	✓				Insurance	Not Present (Insurance Valid)	TF1	1
Setc. Setc		-				NOT	N (D (MOT)(E)	T00	4
Documents, etc. Document V5 Tariff Card v6 Document V5 Tariff Card v6 Document V6 Document V5 Document V6 Document V7 Docu	✓	✓			· ·	MOT	Not Present (MOT Valid)	TG2	1
etc. Document V5 Registration Document V5 Not Present T11 1		-				- · · · ·	N. d.:	T114	4
Documents, etc. Document V5 Not Present TI1 1	V	~			· ·		Not in operators name	IH1	1
etc. Document V5 V							Not Decorat	TIA	4
V	•	v					Not Present	111	1
If meter fitted etc. ✓ Documents, etc. Drivers ID Card Not Present TK5 5 ✓ Documents, etc. Drivers ID Card Incorrectly Displayed TK3 3 ✓ Documents, etc. Licence plate etc. Not Present TL5 5 ✓ Documents, etc. Licence plate etc. Incorrectly Displayed TL3 3 ✓ Documents, etc. Taxi Sign Not Present / Incorrectly TM3 3 ✓ ✓ Taximeter Meter Unsealed (Not 'False or Unjust' and with Reasonable Excuse) TN3 3 ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ Safety+ Standards First aid kit Not Present TQ1 1	./	-/					Not Drocont / Illogible	TIO	2
meter fitted V V Documents, etc. Docum	•				· ·	Tariii Card	Not Present / Illegible	133	3
fitted TK5 Fire Fire Safety+ Standards Safety+ Safety+ Standards Safety+					eic.				
✓ Documents, etc. Drivers ID Card Not Present TK5 5 ✓ Documents, etc. Drivers ID Card Incorrectly Displayed TK3 3 ✓ Documents, etc. Licence plate etc. Not Present TL5 5 ✓ Documents, etc. Licence plate etc. Incorrectly Displayed TL3 3 ✓ Documents, etc. Taxi Sign Not Present / Incorrectly Displayed TM3 3 ✓ ✓ Taximeter Meter Unsealed (Not 'False or Unjust' and with Reasonable Excuse) TN3 3 ✓ Safety+ Standards Extinguisher Not Present TO1 1 ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ Safety+ Standards First aid kit Not Present TQ1 1									
etc. Card Documents, etc. Documents, etc. Documents, et		nited	√	√	Documents	Drivers ID	Not Present	TK5	5
✓ ✓ Documents, etc. Drivers ID Card Incorrectly Displayed TK3 3 ✓ ✓ Documents, etc. Licence plate etc. Not Present TL3 3 ✓ Documents, etc. Licence plate etc. Incorrectly Displayed TL3 3 ✓ Josphayed TM3 3 ✓ Josphayed TM3 3 <				,			Not i resent	110	0
etc. Documents, etc. Not Present / Incorrectly Displayed TM3 3 TM3 3 TN3 3 Safety- Fire Extinguisher Safety+ Standards Safety+ Standards Safety+ Standards Safety+ Standards Safety+ Standards First aid kit Not Present TQ1 1			✓	✓			Incorrectly Displayed	TK3	3
✓ ✓ Documents, etc. Licence plate etc. Not Present TL5 5 ✓ ✓ Documents, etc. Licence plate etc. Incorrectly Displayed TL3 3 ✓ ✓ Documents, etc. Taxi Sign Not Present / Incorrectly Displayed TM3 3 ✓ ✓ Taximeter Meter Unsealed (Not 'False or Unjust' and with Reasonable Excuse) TN3 3 ✓ ✓ Safety+ Standards Fire extinguisher Not Present TO1 1 ✓ ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ ✓ Safety+ Standards First aid kit Not Present TQ1 1							sorrosay Diopiayou	1110	
etc. Documents, etc. Documents, etc. Taxi Sign Not Present / Incorrectly Displayed TM3 TM3 TM3 TM3 TM3 TM3 TM3 TM	√	✓					Not Present	TI 5	5
✓ Jocuments, etc. Licence plate etc. Incorrectly Displayed TL3 3 ✓ Jocuments, etc. Taxi Sign Displayed Not Present / Incorrectly Displayed TM3 3 ✓ ✓ Taximeter Meter Unsealed (Not 'False or Unjust' and with Reasonable Excuse) TN3 3 ✓ ✓ Safety+ Fire extinguisher Not Present TO1 1 ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ Safety+ Standards First aid kit Not Present TQ1 1						Licerios piate	1100111000110	''	
etc. Documents, etc. Taxi Sign Displayed TM3 Total Displayed TM3 Displayed TM3 Total Displayed Total Display	√	✓				Licence plate	Incorrectly Displayed	TI 3	3
✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ Taximeter Meter Unsealed (Not 'False or Unjust' and with Reasonable Excuse) TN3 3 ✓ ✓ ✓ Safety+ Standards Fire extinguisher Not Present TO1 1 ✓ ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ ✓ Safety+ Standards First aid kit Not Present TQ1 1 ✓ ✓ Safety+ Standards First aid kit Not Present TQ1 1					· ·	2.551100 plato		5	
etc. Displayed Unsealed (Not 'False or Unjust' and with Reasonable Excuse) Safety+ Standards Safety+ Standards Safety+ Standards Safety+ Standards Safety+ Standards Fire extinguisher Unacceptable Standard TO1 TO1 Unacceptable Standard TP1 Unacceptable Standard TP1 Standards TQ1 TQ1 TQ1 TQ1 TQ1 TQ1 TQ1 TQ	✓					Taxi Sign	Not Present / Incorrectly	TM3	3
✓ ✓ Taximeter Meter Unsealed (Not 'False or Unjust' and with Reasonable Excuse) TN3 3 ✓ ✓ Safety+ Standards Fire extinguisher Not Present TO1 1 ✓ ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ ✓ Safety+ Standards First aid kit Not Present TQ1 1 Standards Standards Not Present TQ1 1					· ·		· · · · · · · · · · · · · · · · · · ·		
If meter fitted Safety+ Standards Fire extinguisher Not Present TO1 1 ✓ ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ ✓ Safety+ Standards Extinguisher Not Present TQ1 1 ✓ ✓ Safety+ Standards First aid kit Not Present TQ1 1	✓	✓	√	√		Meter		TN3	3
meter fitted ✓ ✓ Safety+ Fire extinguisher ✓ ✓ Safety+ Fire Unacceptable Standard ✓ ✓ Safety+ Fire Unacceptable Standard ✓ ✓ Safety+ First aid kit Not Present ✓ TQ1 1		If							
fitted ✓ ✓ Safety+ Fire Not Present ✓ ✓ Safety+ Fire Unacceptable Standard ✓ ✓ Safety+ Fire Unacceptable Standard ✓ ✓ Safety+ First aid kit Not Present ✓ TQ1 1 Standards									
✓ ✓ Safety+ Standards Fire extinguisher Not Present TO1 1 ✓ ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ ✓ Safety+ Standards First aid kit Not Present TQ1 1 Standards Standards TQ1 1									
Standards extinguisher ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ Safety+ Standards First aid kit Not Present TQ1 1	✓				Safety+	Fire	Not Present	TO1	1
✓ ✓ Safety+ Standards Fire extinguisher Unacceptable Standard TP1 1 ✓ ✓ Safety+ Standards First aid kit Not Present TQ1 1						extinguisher			
Standards extinguisher Safety+ First aid kit Not Present TQ1 1 Standards	✓	✓			Safety+		Unacceptable Standard	TP1	1
✓ ✓ Safety+ First aid kit Not Present TQ1 1 Standards		<u> </u>			•	extinguisher	·	Ш	
	√	✓			Safety+		Not Present	TQ1	1
✓					Standards				
	✓	✓			Appearance/	Spare Wheel	Not Present	TR1	1

	Applicability		Defect			Penalty		
Оре	erator	Dri	ver	Category	Category Sub- Descriptor		Code	Points
Taxi	PHC	Taxi	PHC		Category			
				Utility				
√	✓	✓	>	Appearance/ Utility	External Cleanliness	Unacceptable Standard	TS1	1
√	✓			Appearance/ Utility	External Appearance	Unacceptable Standard	TT1	1
√	✓			Appearance/ Utility	Advertising	Unacceptable Standard (Honest, Decent & Truthful)	TU2	2
√	✓	~	√	Appearance/ Utility	Internal Cleanliness	Unacceptable Standard	TV2	2
√	✓			Appearance/ Utility	Internal Appearance	Unacceptable Standard	TV1	1
√	✓			Appearance/ Utility	Controls & Fittings	Unacceptable Standard	TW1	1
✓	√	✓	√	Appearance/ Utility	Drivers Cleanliness / Appearance	Unacceptable Standard	TX1	1
√	✓	√	✓	Licensee Behaviour	Other Breach of Conditions / Act	Written Warning	TY5	5
√	√	✓	✓	Licensee Behaviour	Other Breach of Conditions / Act	Oral Warning/ Written Notice	TY3	3
√	√			Licensee Behaviour	Accident Damage	Failure to Report	TZ2	2

HIGHLAND COUNCIL - TAXI/PHC VEHICLE TEST REPORT FORM

DATE OF INSPECTION	Thursday 4 March 2021	INSPECTION Inverness MO Street, Invern		OT Centre, 36 Shore ness	
TIME OF INSPECTION	1000 hours	VEHICLE OWNER	Pawel Wyder	ka	
INSPECTION REF NO.	-	ADDRESS			
TAXI/PHC LICENCE NO.	IV 785	POSTCODE & TEL. NO.			
TYPE OF INSPECTION	6 mth Combined	INSPECTION CARRIED C	<u>OUT</u>	Combined	
VEHICLE DETAILS		(Council Test/Combined Test/Retest etc)			
REGISTRATION No.	ST13 VAY	RECEIPT NO(s)		4J6SC9978981	
MAKE & MODEL	Ford Galaxy	FEE PAID		£134	
VEHICLE COLOUR	Silver	MILEAGE		111901	
DATE OF FIRST REG	02/08/2013	FUEL TYPE		Diesel	
ENGINE SIZE	1997	TYRE SIZE		215/60R16	
CHASSIS NO	WFOMXXGBWMDB3630	TAXI METER SERIAL NO		1606895	
NO OF PASSENGER SEATS	6	VEHICLE EXAMINER J		JJ MacFarlane	

ARE 'PRE-BOOKED ONLY' STICKERS BEING DISPLAYED ON EACH SIDE OF THE VEHICLE (PHC'S ONLY)

N/A

	TEST RESULTS	MOT CERTIFICATE NUMBER		
MOT	FAIL			
SAFETY ASPECTS	FAIL	*WARNING In the opinion of the		
APPEARANCE & UTILITY	PASS	examiner, the vehicle is dangerous to drive because of the defects listed in box A above *Delete if not applicable.		
Overall Test Result FAIL				

IMPORTANT: PLEASE READ THE NOTES OVERLEAF FOR INFORMATION AS TO WHAT ACTION (IF ANY) IS REQUIRED TO BE UNDERTAKEN BY YOU THE VEHICLE OPERATOR

A: SAFETY ASPECTS (FAIL POINTS)

NS Parking Brake has no effort	
NS Parking Brake cable broken at caliper	
Parking Brake efficiency below requirements	
Exhaust emissions exceed manufacturer's specified limit 0.51	

Has the plate been removed from the vehicle: No

B: FAULTS (Appearance & Utility Standard) MUST be rectified within 21 days.

C: Observations <u>for information only</u>						



Reference No.
CGSA/ () 8 9 ()

CIVIC GOVERNMENT (SCOTLAND) ACT 1982 SECTION 11(2) STATUTORY NOTICE

(Taxi and Private Hire Cars)
(Safety of Vehicles and Fitness/Accuracy of Taximeters)
Name

Licence Holders Details

Pavel Wyderka

Address

Authorised Officer's Full Name:

Adam Smeaton

Being an Officer authorised by Highland Council for the purposes of Section 11 of the Civic Government (Scotland) Act 1982

Official Address

of, Highland Council, TEC Services, Trading Standards Unit, 38 Harbour Road, Inverness, IV1 1UF

Hereby give you notice that I am not satisfied that

Vehicle Details:		
	Ford Galaxy ST13 VAY	
Licence No:		,
	11 0785	

^{*} is safe for the carriage of passengers

* is fitted with a taximeter which is fit for its purpose and/or accurate The reasons for my said conclusions are:

NS Parking Brake has no effort

NS Parking Brake cable broken at caliper

Parking Brake efficiency below requirements

Exhaust emissions exceed manufacturer's specified limit 0.51

* Your Licence (identified above) to operate a *(Taxl/Private Hire Car), is hereby suspended with immediate effect.

You have a period of 28 days from the date of this Notice to satisfy an authorised officer of the Council or a Police Officer that the above matters have been rectified. Failure to do so will result in the automatic suspension of the unexpired portion of the duration of the said licence.

* You are required to submit the said vehicle *(and taximeter) for further inspection and test at:

Council Inspection Garage upon rectification of faults

Signature of Authorised Officer

A Smeaton 04/03/21

Date

* Delete as appropriate

DATE OF INSPECTION	Friday 5 March 2021	INSPECTION Inverness Mo LOCATION Street, Inver		OT Centre, 36 Shore ness	
TIME OF INSPECTION	1600 hours	VEHICLE OWNER	Pawel Wyder	rka	
INSPECTION REF NO.	-	ADDRESS			
TAXI/PHC LICENCE NO.	IV 785	POSTCODE & TEL. NO.			
TYPE OF INSPECTION	RE-TEST	INSPECTION CARRIED C	OUT .	Retest	
VEHICLE DETAILS		(Council Test/Combined Te	st/Retest etc)		
REGISTRATION No.	ST13 VAY	RECEIPT NO(s)		N/A	
MAKE & MODEL	Ford Galaxy	FEE PAID N/A		N/A	
VEHICLE COLOUR	Silver	MILEAGE 1		11924	
DATE OF FIRST REG	02/08/2013	FUEL TYPE		Diesel	
ENGINE SIZE	1997	TYRE SIZE		215/60R16	
CHASSIS NO	WFOMXXGBWMDB3630	TAXI METER SERIAL NO 1		160895	
NO OF PASSENGER SEATS	6	VEHICLE EXAMINER J.		JJ MacFarlane	

(PHC SUNLI)		
	TEST RESULTS	MOT CERTIFICATE NUMBER
MOT	PASS	
SAFETY ASPECTS	FAIL	
APPEARANCE & UTILITY	PASS	
Overall Test Result		FAIL

N/A

ARE 'PRE-BOOKED ONLY' STICKERS BEING DISPLAYED ON EACH SIDE OF THE VEHICLE

IMPORTANT: PLEASE READ THE NOTES OVERLEAF FOR INFORMATION AS TO WHAT ACTION (IF ANY) IS REQUIRED TO BE UNDERTAKEN BY YOU THE VEHICLE OPERATOR

A: SAFETY ASPECTS (FAIL POINTS)

Exhaust emissions exceed manufacturer's specified limit 0.51				

Has the plate been removed from the vehicle: No

B	FAULT	S (App	earance (&	Utility	y Stai	ndard)	MU	JST	be	rectifie	d w	ithin	21	day	ys.
---	-------	--------	-----------	---	---------	--------	--------	----	-----	----	----------	-----	-------	----	-----	-----

C: Observations for information only

DATE OF INSPECTION	Friday 12 March 2021	INSPECTION LOCATION		Inverness MOT Centre, 36 Shore Street, Inverness		
TIME OF INSPECTION	1300 hours	VEHICLE OWNER Pawel Wyder		ka		
INSPECTION REF NO.	-	ADDRESS				
TAXI/PHC LICENCE NO.	IV 785	POSTCODE & TEL. NO.				
TYPE OF INSPECTION	6 month combined 2 nd re-test	INSPECTION CARRIED OUT (Council Test/Combined Test/Retest etc)		Combined		
VEHICLE DI	ETAILS					
REGISTRATION No.	ST13 VAY	RECEIPT NO(s)		4J6D19935695= £74.00 4J2W19926476= £54.85		
MAKE & MODEL	Ford Galaxy	FEE PAID		£108.85		
VEHICLE COLOUR	Silver	MILEAGE		112383		
DATE OF FIRST REG	02/08/2013	FUEL TYPE		Diesel		
ENGINE SIZE	1997	TYRE SIZE		215/60R16		
CHASSIS NO	WFOMXXGBWMDB3630	TAXI METER SERIAL NO		160895		
NO OF PASSENGER SEATS	6	VEHICLE EXAMINER		JJ MacFarlane		

(PHC'S ONLY)		
	TEST RESULTS	MOT CERTIFICATE NUN

ARE 'PRE-BOOKED ONLY' STICKERS BEING DISPLAYED ON EACH SIDE OF THE VEHICLE

	TEST RESULTS	MOT CERTIFICATE NUMBER		
MOT	PASS	3385 3490 7411		
		11.03.2021		
SAFETY ASPECTS	PASS			
APPEARANCE & UTILITY	PASS			
Overall Test Result PASS				
IMPORTANT: PLEASE READ THE NOTES OVERLEAF FOR INFORMATION AS TO WHAT ACTION (IF ANY) IS REQUIRED				

IMPORTANT: PLEASE READ THE NOTES OVERLEAF FOR INFORMATION AS TO WHAT ACTION (IF ANY) IS REQUIRED TO BE UNDERTAKEN BY YOU THE VEHICLE OPERATOR

A: SAFETY ASPECTS (FAIL POINTS)				
Has the plate been removed from the vehicle: No				

B: FAULTS (Appearance & Utility Standard) MUST be rectified within 21 days.			

C: Observations for information only					

HIGHLAND COUNCIL – TAXI/PHC VEHICLE TEST REPORT FORM

Examiners Signature JJ MacFarlane

Date 12.03.2021



Mr Pawel Wyderka

Please ask for Bobby Smeaton

Direct dial

e-mail

Your ref 11 0785

Our ref

Date

22 April 2022

Bobby.smeaton@highland,gov.uk

Dear Mr Wyderka

Civic Government (Scotland) Act 1982 Taxi and Private Hire Car (PHC) Licensing Provisions Trading Standards Penalty Points System

Trading Standards operates a Penalty Points System to help in the assessment of the level of compliance shown by each Operator in relation to Conditions 1 and 2 of an Operator's licence which require your licensed vehicle to be maintained to the Council's standard. Faults identified either by the Council's Contractor during inspection or by Trading Standards staff during spot checks attract penalty points. These points are totalled over a two-year rolling period and should the total pass 20 points the operator will be reported to the appropriate Licensing Committee for breach of Licence Conditions.

Your licensed vehicle, plate number 11 0785, has accumulated 10 points. Should further points be added so that the total becomes 20 or more, before two years from the date of the first points accrued, please be aware that you will find yourself the subject of a report to your Licensing Committee.

Should you have any queries please do not hesitate to contact me.

Yours sincerely

Bobby Smeaton Enforcement Officer

Production 7 - Taxi Test Report 09/09/2021 HIGHLAND COUNCIL - TAXI/PHC VEHICLE TEST REPORT FORM

DATE OF INSPECTION	Thursday 09 September 2021			ess MOT Centre, 36 Shore Inverness	
TIME OF INSPECTION	1430 hours	VEHICLE OWNER Pawel Wy		erka	
INSPECTION REF NO.	-	ADDRESS			
TAXI/PHC LICENCE NO.	IV 785	POSTCODE & TEL. NO.			
TYPE OF INSPECTION 6 mth Council		INSPECTION CARRIED O	UT	COUNCIL TEST	
VEHICLE DE	ETAILS	(Council Test/Combined Test/Retest etc)			
REGISTRATION No.	ST13 VAY	RECEIPT NO(s)		4J6D19940363	
MAKE & MODEL	Ford Galaxy	FEE PAID		£114.00	
VEHICLE COLOUR	Silver	MILEAGE		128388	
DATE OF FIRST REG	02/08/2013	FUEL TYPE		DIESEL	
ENGINE SIZE	1997	TYRE SIZE		215/65 R16	
CHASSIS NO	WFOMXXGBWMDB3630	TAXI METER SERIAL NO		16-06895	
NO OF PASSENGER SEATS	6	VEHICLE EXAMINER		Gareth MacMillan	

ARE 'PRE-BOOKED ONLY' STICKERS BEING DISPLAYED ON EACH SIDE OF THE VEHICLE (PHC'S ONLY)

	TEST RESULTS	MOT CERTIFICATE NUMBER		
МОТ	N/A	N/A		
SAFETY ASPECTS	FAIL			
APPEARANCE & UTILITY	PASS			
Overall Test Result	FAIL			
IMPORTANT: PLEASE READ THE NOTES OVERLEAF FOR INFORMATION AS TO WHAT ACTION (IF ANY) IS REQUIRED TO BE UNDERTAKEN BY YOU THE VEHICLE OPERATOR				

A: SAFETY ASPECTS (FAIL POINTS)

Nearside rear handbrake not working		

Has the plate been removed from the vehicle: NO

B: FAULTS (Appearance & Utility Standard) MUST be rectified within 21 days.			

C: Observations for information only

Offside and nearside rear trailing arm bushes worn	Nearside number plate light not working		



Reference No. CGSA/ 0890

e

Date

* Delete as appropriate

CIVIC GOVERNMENT (SCOTLAND) ACT 1982

	SECTION 11(2) STATUTORY NOTICE
Licence Holders Details	(Taxi and Private Hire Cars) (Safety of Vehicles and Fitness/Accuracy of Taximeters) Name
	Pawel Wyderka
	Address
Authorised Officer's Full Nan	S I,
	Adam Smeaton
	Being an Officer authorised by Highland Council for the purposes of Section 11 of the Civic Government (Scotland) Act 1982
Official Address	of, Highland Council, TEC Services, Trading Standards Unit, 38 Harbour Road, Inverness, IV1 1UF
	Hereby give you notice that I am not satisfied that
	Ford Galaxy ST13 VAY
	Licence No: 11 0785
	* is safe for the carriage of passengers
	* is fitted with a taximeter which is fit for its purpose and/or accurate
	ny said conclusions are:
N/S/R handbr	ake not working
Your Licence (iden	ified above) to operate a *(Taxi/Private Hire Car), is hereby suspended with immediate effec
ou have a period of 2 Officer that the above	days from the date of this Notice to satisfy an authorised officer of the Council or a Police natters have been rectified. Failure to do so will result in the automatic suspension of the duration of the said licence.
	submit the said vehicle *(and taximeter) for further inspection and test at:
me and Place	the second of the second secon
	Council Inspection Garage upon rectification of faults
gnature of Authorised Offic	ti"
	A Smeaton 09-09-21

Production 9 - Taxi Test Report 10/09/2021 HIGHLAND COUNCIL - TAXI/PHC VEHICLE TEST REPORT FORM

DATE OF INSPECTION	Friday 10 th September 2021	INSPECTION LOCATION	Inverness MO Street, Invern	OT Centre, 36 Shore
TIME OF INSPECTION	1700 hours	VEHICLE OWNER	Pawel Wyder	ka
INSPECTION REF NO.	-	ADDRESS		
TAXI/PHC LICENCE NO.	IV 785	POSTCODE & TEL. NO.		
TYPE OF INSPECTION	RE TEST	INSPECTION CARRIED OUT		RE TEST
VEHICLE DI	ETAILS	(Council Test/Combined Test	st/Retest etc)	
REGISTRATION No.	ST13 VAY	RECEIPT NO(s)		N/A
MAKE & MODEL	Ford Galaxy	FEE PAID		FREE
VEHICLE COLOUR	Silver	MILEAGE		128400
DATE OF FIRST REG	02/08/2013	FUEL TYPE		DIESEL
ENGINE SIZE	1997	TYRE SIZE		215/65 R16
CHASSIS NO	WFOMXXGBWMDB3630	TAXI METER SERIAL NO		16-06895
NO OF PASSENGER SEATS	6	VEHICLE EXAMINER		D Scott

ARE 'PRE-BOOKED ONLY' STICKERS BEING DISPLAYED ON EACH SIDE OF THE VEHICLE (PHC'S ONLY)

	TEST RESULTS	MOT CERTIFICATE NUMBER	
МОТ	N/A	N/A	
SAFETY ASPECTS	PASS		
APPEARANCE & UTILITY	PASS		
Overall Test Result pass			
IMPORTANT: PLEASE READ THE NOTES OVERLEAF FOR INFORMATION AS TO WHAT ACTION (IF ANY) IS REQUIRED TO BE UNDERTAKEN BY YOU THE VEHICLE OPERATOR			

A: SAFETY ASPECTS (FAIL POINTS)

Has the plate been removed from the vehicle: NO

B : FAULTS (Appearance	& Utility Standard) MUST	The rectified within 21 days.

C: Observations for information only

Offside and nearside rear trailing arm bushes worn	Nearside number plate light not working

HIGHLAND COUNCIL - TAXI/PHC VEHICLE TEST REPORT FORM

DATE OF INSPECTION	Wednesday 09 March 2022	INSPECTION LOCATION		os, Great North Bridge, Dingwall
TIME OF INSPECTION	1145 hours	VEHICLE OWNER	Pawel Wyder	ka
INSPECTION REF NO.	-	ADDRESS		
TAXI/PHC LICENCE NO.	IV 785	POSTCODE & TEL. NO.		
TYPE OF INSPECTION	6 mth Combined	INSPECTION CARRIED O	<u>UT</u>	combined
VEHICLE DE	ETAILS	(Council Test/Combined Test	st/Retest etc)	
REGISTRATION No.	ST13 VAY	RECEIPT NO(s)		4j3in9961751
MAKE & MODEL	Ford Galaxy	FEE PAID		134.00
VEHICLE COLOUR	Silver	MILEAGE		143226
DATE OF FIRST REG	02/08/2013	FUEL TYPE		diesel
ENGINE SIZE	1997	TYRE SIZE		215/65/16
CHASSIS NO	WFOMXXGBWMDB3630	TAXI METER SERIAL NO		1606895
NO OF PASSENGER SEATS	6	VEHICLE EXAMINER		P foster

ARE 'PRE-BOOKED ONLY' STICKERS BEING DISPLAYED ON EACH SIDE OF THE VEHICLE (PHC'S ONLY)

YES/NO

	TEST RESULTS	MOT CERTIFICATE NUMBER
MOT	fail	
SAFETY ASPECTS	fail	
APPEARANCE & UTILITY	pass	
Overall Test Result		fail

IMPORTANT: PLEASE READ THE NOTES OVERLEAF FOR INFORMATION AS TO WHAT ACTION (IF ANY) IS REQUIRED TO BE UNDERTAKEN BY YOU THE VEHICLE OPERATOR

A: SAFETY ASPECTS (FAIL POINTS)

Emissions above limits	Both rear axle front bushes perished
Fuel cap missing	o/s headlight too high
Handbrake readings below limits	No rubber on brake pedal
Service brake below limits	

Has the plate been removed from the vehicle: Yes/No

B: FAULTS (Appearance & Utility Standard) MUST be rectified within 21 days.

First aid kit expired (2021)	

C: Observations for information only

Age related marks	No top sign fitted

Examiners Signature...p foster.....

Date9	/3/22	_

Signature of Authorised Officer | J McLean

Date 09.03.2022



CIVIC GOVERNMENT (SCOTLAND) ACT 1982 SEC CTION 11(2) STATUTORY NOTICE

(Taxi and Private Hire Cars)
(Safety of Vehicles and Fitness/Accuracy of Taximeters)

Licence Holders Details					
Name Mi	r Pawel Wyderka				
	,				
L					
Authorised Officer's Full Name; I,	Jordan Mclean Being an Officer authorised by Highland Council for the purposes of Section 11 of the Civic Government (Scotland) Act 1982				
Official Address	Of, Highland Council, Trading Standards Unit, 38 Harbour Road, Inverness, IV1 1UF				
	Hereby give you notice that I am <u>not</u> satisfied that				
Vehicle Details: Ford Galaxy – ST13 VAY					
Licence No: 11 0785					
	* Is safe for the carriage of passengers				
	* is fitted with a taximeter which is fit for its purpose and/or accurate				
The reason for my said conclusions Emissions above limits					
are:	Fuel cap missing				
Handbrake readings below limits					
Service brake below limits					
Both rear axle front bushes perished					
	o/s headlight too high				
	No rubber on brake pedal				
	First aid kit expired (2021)				
* Your Licence (identified above) to op	erate a *(Taxi/Private Hire Car), is hereby suspended with immediate effect.				
· · · · · · · · · · · · · · · · · · ·	date of this Notice to satisfy an authorised officer of the Council or a Police Officer ified. Failure to do so will result in the automatic suspension of the unexpired nce.				
* You are required to submit the said v	rehicle *(and taximeter) for further inspection and test at:				
Time and place	Council Inspection Garage upon rectification of faults				

DATE OF INSPECTION	Monday 21 March 2022		INSPECTION LOCATION		tos, Great North Bridge, Dingwall		
TIME OF INSPECTION	1200 hours		VEHICLE OWNER	Pawel Wyderka			
INSPECTION REF NO.	-		ADDRESS				
ΓΑΧΙ/PHC LICENCE NO.	IV 785		POSTCODE & TEL. NO				
TYPE OF INSPECTION	Re-test		INSPECTION CARRIED OUT		retest		
VEHICLE DETAILS		(Council Test/Combined Test/Retest etc)					
REGISTRATION No.	ST13 VAY		RECEIPT NO(s)		6sc5728	6sc5728109	
MAKE & MODEL	Ford Galaxy		FEE PAID		54.00	54.00	
VEHICLE COLOUR	Silver		MILEAGE	MILEAGE		143938	
DATE OF FIRST REG	02/08/2013		FUEL TYPE		diesel		
ENGINE SIZE	1997		TYRE SIZE		215/65/16		
CHASSIS NO	WFOMXXGBWMDB3630		TAXI METER SERIAL NO		1606895		
NO OF PASSENGER SEATS	6		VEHICLE EXAMINER		P foster		
ARE `PRE-BOOKED ONLY' S (PHC'S ONLY)	STICKERS BEIN	IG DISF	PLAYED ON EACH SIDE	OF THE VEHIC	LE	YES/N	
		r.	TEST RESULTS	MOT CERTIFI	ICATE NU	MBER	
MOT			n/a				
SAFETY ASPECT	SAFETY ASPECTS		pass				
APPEARANCE & UT	ILITY		pass				
Overall Test	Result		<u>I</u>	<mark>)ass</mark>			
IMPORTANT: PLEASE READ TI FO BE UNDERTAKEN <u>BY YOU</u>				VHAT ACTION (II	F ANY) IS I	REQUIRE	
A: SAFETY ASPECTS (FAIL	POINTS)						

B: FAULTS (Appearance & Utility Standard) MUST be rectified within 21 days.

C: Observations for information only			
Age related marks	No top sign fitted		

Examiners Signature..p foster.....

Date..21/3/22.....